

WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

Quotation

DATE: 2/5/2024
VEHICLE NO: PD596L
DRIVER: TEO SENG HOW
TYPE OF CLAIM: CLAIM 3 P
PREPARED BY: KAMARUL

LOCATION: Gul Workshop
Q REF NO:
DEPARTMENT: BUS (AIRPORT)
ACCIDENT DATE: 11/4/2024
REF No: JW/0424/185

S/N	Description	Qty	Cost per Unit	Total cost W/O Gst
SPARE PARTS				
1	L/H/S TAIL LAMP <i>SLW ✓</i>	1	180	180.00
LABOUR				
1	REMOVE AND INSTALL NEW L/H/S TAIL LAMP	1	50	50.00 30
2	REPAIR AND PANEL BEAT REAR BUMPER DENTED	1	280	280.00 250
3	REPAIR AND PANEL BEAT L/H/S BOTTOM PANEL	1	150	150.00 80X
4	REPAIR AND PANEL BEAT L/H/S PANEL	1	180	180.00
5	REPAIR AND PANEL BEAT L/H/S CORNER PANEL	1	100	100.00 80
SPRAY PAINTING				
1	PUTTY AND SPRAY PAINTING REAR BUMPER	1	350	350.00 250
2	PUTTY AND SPRAY PAINTING L/H/S PANEL	1	200	200.00
Total Amount				1490.00

180
102
162

990

Total cost subjected to GST
Remarks: LOU 03 DAYS

Signature of Workshop

Signature of Department Head

Signature of Claim

Monday 24/06/24 @ 1400hrs (LKK.)

1 / 1

162
990
1152

Repair
Hy 900 10068

3 days

24/06/24

Repair after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature