(08/11	/13)	wef	
100	DEC	DV. MC/CL	

REF: CD/ LPC 2409 OF 18/Uma3

ASSIGNMENT

From: Date:	Veh No: FB79803M Yr Regn: 06/07/19
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or AD Venture S
To Inspect Vehicle No: F879863M	Make: K. T. M 1290 c.c /30/
at Workshop m/s BHM	Colour Orange / Blede A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: VBKV79402JM992260
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or Access
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 120/70 2019
(Policy Condition)	R: 170/60 n 17
Remark: The veh had commenced its N/S O/S	(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SÚMÍ /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal.
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. 03/08/14 D.O.I. 30/08/2×
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: LAA & VEST	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MU\$19-224.	
4/10/24 inhund stephane 7/6	TAL 1085
4/0/24 inhund stephane 7/6 8	02231
* MAV . \$40,000,00 (EST)	* LINECONOMICAL TO DEDAID
	* UNECONOMICAL TO REPAIR * ESTIMATED REPAIR COST L/SUM \$22,900.0
* NV : \$16,549.00 (EST)	E011WATED ILLI AIIX 0001 E/00W \$22,300.0
14.0 . φ10,010.00 (ΕΘ1)	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fed	
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$



Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE

MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL

WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

3rd Oct 2024

Lonpac Insurance Bhd 300 Beach Road, The Concourse, #17-04/06, Singapore 199555

To who it may concern,

Accident between FBT9863M & XD9447E on 3 Sep 24

I am writing to inform you that, following a thorough assessment, our client's vehicle has been deemed beyond economic repair. The damage sustained from the accident has resulted in extensive costs that exceed the vehicle's current market value.

partitional contraction of

Therefore, we have decided not to proceed with repairs.

Thanks.

Regards Stephanie Gan Insurance Manager

NOT Authoral
SUPPLY
TOTAL 1085

KK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





Co.Reg.No: 197000288K



MOTORCYCLE ACCESSORIES | SERVICE CENTRE MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES| INSURANCE SALES

Customer:

LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702

ATTN: LONPAC INSURANCE BHD

QUOTATION

NO.: 47817

30/09/24

DATE: 30/09/2024

CLAIM NO.: 12603

POLICY NO.: MC/01230958/01

Tans? FROM: STEPHANDE

VEHICLE NO.

: FBT9863M

MAKE/MODEL

: K.T.M / 1290 SUPER ADVE

(Page 1 of 7)

					(i ago i	
5/N	Description	Action	Qty	Unit Price	W	nount
	AIR DUCT INTAKE RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$94.00	Cre	94.00 _
	AIR INTAKE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	Cre 1	55.00
	AXLE FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	2	80.00
	BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$1,550.00	1,5	550.00
	BOLT M5X14 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$7.00	ru	14.00
	BOLT STEERING HEAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	nu	71.00
	BRACKET FUEL HOSE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00		71.00
	BRACKET UNDER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,085.00	crepsy1,0	085.00
	BRAKE FLUID DOT5.1 0,25L P/N: 63833 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	?	55.00







Quota	ation Nos. : 47617				(3	, ,
S/N	Description	Action	Qty	Unit Price	33	<u>Amount</u>
10	CAMERA (V_SYS) M6 (WIFI VERSION) P/N: 56377 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	7	388.00
11	CLIP EXHAUST 60MM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	7	71.00
12	COLLAR SCREW - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	7	11.00
13	COMPARTMENT STORAGE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	CM	210.00
14	COVER DASHBOARD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	(re	85.00
15	COVER ENGINE (R&G) CASE(RH) KTM ADVENTURE P/N: 50757	REPLACE	1.00	\$232.00	cul	232.00
16	- (REPORTED BY MECHANIC) COVER FUEL TANK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,008.00	?.	1,008.00
17	COVER HEADLAMP LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$218.00	cre	218.00
18	COVER HEADLAMP RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$218.00	CM	218.00
19	COVER HEADLAMP UNDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	cre	55.00
20	COVER HEADLIGHT MASK HOLDER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$44.00	mye	88.00
21	COVER HORN FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$67.00	CM	67.00
22	COVER INNER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	(re	164.00
23	COVER INNER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	CM	164.00
24	COVER INTAKE DUCT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	CNR	85.00
25	COVER INTAKE DUCT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	cvo	85.00







Quotation Nos.: 47817

Quota	ation Nos.: 4/81/				(. 5.5 - 7
<u>S/N</u> 26	Description COVER INTAKE PORT FOR LH - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	Unit Price \$55.00	De S55.00
27	COVER INTAKE PORT FOR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	Dye 55.00
28	COVER MUFFLER PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	Cu7 341.00
29	COVER SIDE FRONT UPPER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	CU1 233.00
30	COVER SIDE FRONT UPPER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	(47 233.00
31	COVER SPOILER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,024.00	CNC 1,024.00
32	COVER SPOILER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,024.00	One 1,024.00
33	COVERBUSHING CHAIN PROTECTION - (REPORTED BY MECHANIC)	REPLACE	4.00	\$17.00	68.00 7
34	CRASHBAR SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$961.00	Dye 961.00
35	CROWN HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$876.00	3rf 876.00
36	DAMPER STEERING - (REPORTED BY MECHANIC)	REPLACE	1.00	\$651.00	€ 651.00
37	DAMPER STEERING CLAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$202.00	Dyl 202.00
38	EXHAUST MANIFOLD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,410.00	3,410.00 √
39	EXHAUST PIPE FLANGE GASKET P/N: 63825	REPLACE	2.00	\$55.00	110.00 ?
40	- (REPORTED BY MECHANIC)FOOTREST FRONT RH- (REPORTED BY MECHANIC)	REPLACE	1.00	\$109.00	Cn7 109.00
41	FORK ASSY FRONT SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6,635.00	? 6,635.00







Quotation Nos.: 47817

Quota	ation Nos.: 4/81/				(1 ago 1 01 1)	
<u>S/N</u> 42	Description FORK FRONT SLIDER - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	Unit Price \$141.00	Amoun 141.00	
43	GASKET INTAKE DUCT - (REPORTED BY MECHANIC)	REPLACE	2.00	\$28.00	56.0	o .
44	HANDGUARD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$226.00	CU? 226.0	0
45	HANDLEBAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$550.00	550.0	0 ?
46	HANDLEBAR RISER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$107.00	214.0	?
47	HEADLAMP ADJUSTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.0	?
48	HEADLAMP ADJUSTER THUMBWHEEL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.0	0.
49	HEADLAMP ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,333.00	CM 3,333.0	0
50	HEADLAMP PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$0.00	ner 0.0	0_
51	HEADLAMP SUPPORT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00	Sel 75.0	9_
52	HEADLIGHT MASK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$195.00	M 195.0	0
53	HEADLIGHT SUPPORT TOP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	. 14.0	0
54	HH COLLAR SCREW M8X30 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$11.00	? 22.0	10
55	HORN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$122.00	? 122.0	10
56	IGNITION KEY PROGRAMMING AT KTM AGENT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$745.00	Dy e 745.0	10







Quot	auon 1403 47017				(r age o er r)
S/N	Description	<u>Action</u>	Qty	Unit Price	<u>Amount</u>
57	LABOUR	Supply/Install	50.00	\$85.00	(00) 4,250.00
	P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.				
58	LAMP SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$148.00	CU7 148.00
59	LOCKSET RACE-ON - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,635.00	2,635.00
60	MANIFOLD GASKET P/N: 63849	REPLACE	1.00	\$55.00	55.00
61	- (REPORTED BY MECHANIC) MANIFOLD GASKET 60MM P/N: 63852	REPLACE	1.00	\$63.00	63.00
62	- (REPORTED BY MECHANIC) MASTER CYLINDER PUMP BRAKE RH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,109.00	1,109.00
63	METER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6,665.00	6,665.00
64	MIRROR SET - (REPORTED BY MECHANIC)	REPLACE	2.00	\$256.00	BN 512.00
65	MUDGUARD FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$296.00	Cu) 296.00
66	MUFFLER (LEOVINCE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,140.00	2,140.00
67	MUFFLER PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	۲۸7 71.00
68	NUT SPRING M5 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$11.00	Men 33.00
69	OBU TYPE B (12V) NEW P/N: 82490	REPLACE	1.00	\$341.00	7 341.00
70	- (REPORTED BY MECHANIC) O-RING VITON P/N: 55505	REPLACE	1.00	\$17.00	7 17.00
71	- (REPORTED BY MECHANIC) PEDAL BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$326.00	Red Cu 326.00









Quotation Nos.: 47817

Quota	tion Nos. : 47817				(, -3	, 0 01 17
<u>S/N</u> 72	Description PLATE DISC BRAKE FRONT D=320X4.5 - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	Unit Price \$683.00	?	<u>Amount</u> 683.00
73	POWER SOCKET COMPLETE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	ner	132.00
74	RIM FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,170.00	Sil	2,170.00
75	SCREW M5X12 - (REPORTED BY MECHANIC)	REPLACE	11.00	\$11.00	ner	121.00
76	SCREW M5X17 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	se	11.00
77	SCREW M6X18 8.8 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$13.00	ner	52.00
78	STAND MAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$869.00	(u)	869.00
79	STEERING CONE SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	,	210.00
80	STICKER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	nu	71.00
81	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	REPLACE	1.00	\$30.00	ner	30.00
82	P/N: 32921 - (REPORTED BY MECHANIC) STICKER SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$590.00	ner	590.00
83	SWING ARM SLIDER MOTOVATION - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	enj	233.00
84	SWINGARM ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4,185.00	(47	4,185.00
85	SWINGARM KIT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$249.00	nu	249.00
86	SWITCH HANDLE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,395.00	12	1,395.00







S/N	Description	Action	Qty	Unit Price		Amount
87	TYRE PRESSURE SENSOR P/N: 81401 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$427.00	7	427.00
88	VALVE RIM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	7.	91.00
89	WASHER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	7	10.00
90	WASHER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	?	10.00
91	WASHER THRUST 25X35X0.5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	?	5.00
92	WINDSHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	one	388.00
93	WIRE HARNESS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,790.00	7	2,790.00
		SUB TOTAL GST @ 9 %				51,690.00 55,552.10
		GRAND TOTAL (SGD)			\$6	7,242.10

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

KK Auto Consultants hence notify

the Repairer of the following:

- To recurvey before/after spray pointing
- To display damaged part(s) duffing recurvely
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudica" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed recit is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:









> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	
Vehicle Details	150G
Vehicle No.:	FBT9863M
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Sep 2024
Vehicle Make:	K.T.M.
Vehicle Model:	1290 ADVENTURE S
Primary Colour:	Black
Secondary Colour:	Orange
Manufacturing Year:	2018
Engine No.:	860723423
Chassis No.:	VBKV79402JM992280
Maximum Power Output:	-
Open Market Value:	\$17,070.00
Original Registration Date:	06 Jul 2018
First Registration Date:	06 Jul 2018
ransfer Count:	2
Actual ARF Paid:	\$10,320.00
ntended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
ntended COE Rebate Details	
COE Expiry Date:	05 Jul 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,514.00
COE Rebate Amount:	\$2,451.00
otal Rebate Amount: Message	\$2,451.00

The information contained herein is correct as at 30 Sep 2024

period/s), if you renew your COE.

Motorcycles > Motorcycles for Sale > Class 2



carousell

OO Register Login

Make Offer

Q Search for an item







Dirt Wheel Motor & Credit @dirtv

5.0 ★★★★ (2 reviews)

Oct 2018 KTM 1290 Super Adventure S \$\$22,800 \$\frac{5\frac{5}{25,800}}{25}\$

C Used

កំតំ Meetup

O Dirt Wheel Motoring

Description

Bumped

Make

Туре

2 weeks ago

KTM

Adventure

Registered October 2018 Mileage 36,000km only

Meet-up

O Dirt Wheel Motoring [2

Returns and refunds

Depends on the seller's decision. Not covered by Buyer Protection.

Sign in to make offer

Safety policy

S\$ 22800

Pay only at the meet-up. Transferring money directly to strangers puts you at risk of e-commerce scams.

Advertisement

Meet the seller



Dirt Wheel Motor & Credit

@dirtwheeltampines

- O Joined 5 years ago
- Very Responsive

KTM 1290 Super Adventure R

Reg Date

24/01/2024

Capacity

1301cc

Vehicle Type

Posted on: 23/09/2024

Sport Tourers

Mileage

1867km

Paid Ad

n Dealer Ad

Dealer Ad

SGD \$58888

Details >



KTM 1290 Super Adventure R

Reg Date Vehicle Type 13/06/2017

Sport Tourers

Capacity Mileage 1301cc

64477km

SGD \$21800

Details >

Posted on: 23/08/2024

Paid Ad





KTM 1290 Super Adventure R

Reg Date Vehicle Type 26/10/2017

Capacity

1301cc

Sport Tourers

Mileage

106407km

sgd \$21800

Details >

Posted on: 23/08/2024

A Paid Ad

n Dealer Ad



KTM 1290 Super Adventure S

Reg Date

11/08/2017

Capacity

1301cc

Vehicle Type

Posted on: 03/09/2024

Sport Tourers

Mileage

117787km

Paid Ad

n Dealer Ad

SGD \$16888

Details >



Vehicle Details

CO2 Emission:

Vehicle No. Make / Model FBT9863M K.T.M. / 1290 ADVENTURE S Vehicle Type: Vehicle Attachment 1: P00 - Passenger Motorcycle/Autocycle No Attachment /Moped Vehicle Scheme: Chassis No.: Normal VBKV79402JM992280 Propellant: Engine No.: Petrol 860723423 Motor No.: Engine Capacity: 1301 cc Power Rating: Maximum Power Output: Maximum Laden Weight: Unladen Weight: 460 kg 245 kg Year Of Manufacture: Original Registration Date: 2018 06 Jul 2018 Lifespan Expiry Date: COE Category: D - Motorcycle Quota Premium: COE Expiry Date: \$6,514.00 05 Jul 2028 Road Tax Expiry Date: PARF Eligibility Expiry Date: 05 Jan 2025 Inspection Due Date: Intended Transfer Date: 05 Jul 2025 24 Sep 2024

CEV/VES Rebate Utilised Amount: