

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TR111
 Xiao Tong

TAX INVOICE

ENG YONG HOCK
 236 COMPASSVALE WALK #07-522
 SINGAPORE 540236

Repair Code : CLM18392

Date in : 28/09/2024

Vehicle Num. : SMH6340H

Model : HYUNDAI AD AVANTE 1.6 GLS (A) ELITE

Chassis/Eng# : KMHD841CMKU846883/G4FGJU076284

Contact : 94553455 90628565

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Dehd</i>	1	573.00	✓ 573.00
FRONT BUMPER LH FOGLAMP <i>crackd</i>	1	185.00	✓ 185.00
FRONT BUMPER REINFORCEMENT <i>new</i>	1	717.00	+ 717.00
FRONT BUMPER SIDE AIR DUCT GARNISH LH <i>crackd</i>	1	65.00	✓ 65.00
FRONT BUMPER SIDE AIR DUCT LH <i>Dehd</i>	1	125.00	✓ 125.00
FRONT BUMPER SIDE RETAINER LH <i>crackd</i>	1	40.00	✓ 40.00
FRONT GRILLE <i>new</i>	1	1215.00	+ 1,215.00
FRONT LH FENDER <i>Dehd</i>	1	1227.00	✓ 1,227.00
FRONT LH FENDER INNER SHIELD <i>ton</i>	1	105.00	✓ 105.00
FRONT LH HEADLAMP <i>ct</i>	1	3354.00	✓ 3,354.00
FRONT LH HEADLAMP LOWER BRACKET <i>new</i>	1	35.00	+ 35.00
FRONT LH KNUCKLE ARM	1	390.00	+ 390.00
FRONT LH KNUCKLE ARM BEARING <i>2 new</i>	1	452.00	+ 452.00
FRONT LH SPORT RIM <i>ct</i>	1	933.00	933.00 <i>450(50)</i>
Subtotal before discount			9,416.00
Percentage discount 20%			1,883.20
Sub-total 1			7,532.80
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>

5674
 4539.20
 S.N:450

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ENG YONG HOCK
 236 COMPASSVALE WALK #07-522
 SINGAPORE 540236

Contact : 94553455 90628565

TAX INVOICE

Repair Code : CLM18392
 Date in : 28/09/2024
 Vehicle Num. : SMH6340H
 Model : HYUNDAI AD AVANTE 1.6 GLS (A) ELITE
 Chassis/Eng# : KMHD841CMKU846883/G4FGJU076284

FRONT LH FENDER INNER SHIELD CLIPS - SET <i>New</i>	1	50.00	<i>30</i>	50.00
FRONT LH TYRE <i>at</i>	1	<i>240</i> 380.00	<i>180</i>	380.00
Subtotal before discount				480.00
Percentage discount 0%				0.00
Sub-total 2				480.00
Parts-total				8,012.80

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)
- To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.
- To road test driving, check and resetting wheel alignments system.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

30 80.00
x 120.00
80 100.00
1240 600 1,000.00
500 1,000.00
80 80.00

Labour Total 2,380.00
Parts & Labour Total 10,392.80

*** This is a computer-generated document which requires no signature.***
 LKK Auto Consultants (Singapore) Pte Ltd
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

page 2

Adrian G
H/S 30/09/24
04 Days
total: 6469.20
H/S : 5.1K ✓