

ASS. REG. BY: Taufik

REF: CS/1M/24090520/Top3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP WS / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SKT 8768E

Policy No. MV004733

Claims No. M2405644

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

X	
N/S	O/S
X	

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum. Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
MS Loh

Veh No: SHD4594K Yr Regn: 2019 / 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / (X) Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 551261 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKB3FU403090718

Gen. Cond: (X) Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: (X) In order / Jammed / Leaked / Burnt or

Mod: (X) NIF S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R: 1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 29/9/204

Survey held at Comfort Lodge

Des. of Damages: (X) Front / (X) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/10/24	Taufikh confirmed LS \$2500 (Red 6902.03, 73%)

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report

Date/Time, File Return to? 2) _____

Report Format: _____

Days Of Repair: 3

Re-survey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)

Survey Fee: _____
Transportation: _____
\$ + RS \$ _____
Photos: _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/09/2024
Vehicle Reg. No.:	SHD4594K	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS, 1.5 (A)	Vehicle Reg. Date:	19/12/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZR2G33277	Chassis No:	JTDKB3FU403090718
Odometer:	551261 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	7,450.03
Labour	12.00
Paintwork Labour	1,940.00
Towing	0.00
	0.00
Gross Total (\$\$)	9,402.03
+ GST 9.00% (\$\$)	846.18
Nett Amount (\$\$)	10,248.21

This claim is handled by: LOKE WEI YIENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG

Version: 1.0 (Last Synchronised: 30 Sep 2024)

Parts: 144

TOYOTA PRIUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHD4594K/30/09/2024 13:09**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	de 503.04 FL
2	1		*REAR BUMPER CLIPS	25.00	0.00	ner 22.00 FL
3	1		*REAR BUMPER LOWER COVER	25.00	0.00	de 654.96 FL
4	1		*REAR BUMPER REINFORCEMENT	25.00	0.00	? 378.32 FL
5	1		*REAR BUMPER SIDE RETAINER LH	25.00	0.00	X 94.80 FL
6	1		*REAR BUMPER REFLECTOR LH	25.00	0.00	X 55.00 FL
7	1		*FRONT BUMPER COVER	25.00	0.00	de 499.90 FL
8	1		*FRONT BUMPER CLIPS	25.00	0.00	ner 22.00 FL
9	1		*HEADLAMP LH	25.00	0.00	X 2,735.28 FL
10	1		*HEADLAMP RH	25.00	0.00	X 2,735.28 FL
11	1		*FRT BUMPER REINFORCEMENT	25.00	0.00	? 696.40 FL
12	1		*FRT BUMPER SPONGE	25.00	0.00	? 78.80 FL
13	1		*FRT BUMPER LOWER GRILLE	25.00	0.00	X 166.90 FL
14	1		*FRT BUMPER RADIATOR GRILLE	25.00	0.00	ner 438.00 FL
15	1		*FRT BUMPER GRILLE GARNISH	25.00	0.00	? 186.90 FL
16	1		*RADIATOR GRILLE EMBLEM	25.00	0.00	ner 88.00 FL
17	1		*FRONT BUMPER EXTENSION PLATE	25.00	0.00	? 99.00 FL
18	1		*FRT BUMPER TOWING COVER	25.00	0.00	X 98.80 FL
19	1		*REAR BUMPER RUBBER MAT	0.00	0.00	ner 50.00 F
20	1		*REAR REVERSE SENSOR	0.00	0.00	X 180.00 F
21	1		*FRT NUMBER PLATE WITH TRIM COVER	0.00	0.00	ner 55.00 F

F=Franchise part, L=ListItemDisc.

Sub Total (\$)	9,838.38
- List Item Discount on L Items (\$)	2,388.35
Total Parts (\$)	7,450.03

ComfortDelGro Engineering Pte Ltd/SHD4594K/30/09/2024 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

12.00

Sub Total (S\$)

✓

12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	PANEL BEATING	New	760	1,200.00
2	SPRAY PAINTING CHARGE	New	560	600.00
3	REMOVE & REFIX REVERSE SENSOR	New	30	80.00
4	CHECK LIGHTING	New	K	60.00

Gross Labour Cost (S\$)

1,940.00

ComfortDelGro Engineering Pte Ltd/SHD4594K/30/09/2024 13:09. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphm 92495749
'wp' 1/10/24 @ 230pm
c/s Resurvey after repair
Tanphm @ 1/khaufo.in
03 → 4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: