

# SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SMADMIN@SM-AUTOMOTIVE.SG

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date : 17/01/2023

Estimated repair cost for vehicle no: SCZ9218H TOYOTA COROLLA ALTIS 1.6L CVT

CHASSIS: MR053REH104521208 (2014)

17/01/2023

## SUPPLEMENTARY

S/N	Qty	Items	U/price	Amount
1	1	REAR EXHUAUST MUFFLER <i>Defect</i>	\$956.40	<del>\$956.40</del> <i>810</i>
2	1	REAR EXHUAUST MUFFELR HEAT SHIELD <i>pc on</i>	\$274.60	\$274.60 *
3	1	REAR EXHUAUST RUBBER MOUNTING <i>pc on</i>	\$32.80	\$65.60 *

*810*  
*607.50*

TOTAL :	<u>\$1,296.60</u>
LESS 25 %	<u>\$324.15</u>
SUB-TOTAL :	<u>\$972.45</u>

TOTAL PARTS \$972.45

## Labour charges

1 LABOUR FOR REMOVE & RENEW REAR EXHUAUST MUFFLER

*80*  
~~\$300.00~~

Subtotal :- \$300.00

*Supply by: 687.50* Total:- \$1,272.45

*Adrian Lj*  
*01/10/24.*