

CD/III 24090523/Dua³

COE 27 April 2030

Yeh No: SHC 7007 H Yr Regn: 28 April 2022

Type: ☐ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☒ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Toyota Price: 1798

Colour: Yellow A/C: Insured / Std / NH / NA

Sp. Reading 290618 T/Radio: Insured / Std / NI / NA

Eng/No: 22R.2P82944

CNo: JTDK B3Fu803096442

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Type Size: F: 195/65 R15

R:

N/S	O/S
-----	-----

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO DT

Front

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

DOA 27/09/2024 DOI 01/10/2024

Survey held at Widfrast Woyen

Des. of Damages: Frt / Rear / O/S / N/S / L/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

III SLQ 3161 S

02/01/25 page 2/3 7,900/- with 7 days of 7

☐ : Prel. Report
☐ : Final Report

Resurvey No. of Trip:

Transportation:

29

Site Insp (S

Interview : (\$

Tech. Invs (\$

Weekend (S

$$) \quad S + RS \quad S$$

Photos

10

10

1

Report Format :

Lump Sum / L.B.L. (\$

TOTAL

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 27-Sep-24

INSURANCE: TIS

MODEL: TOYOTA PRIUS G5

VEHICLE NO.: SHC 7007 A

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR TRUNK LID COVER <i>lt</i>	1	\$ 1,577.24	\$1,577.24	✓
REAR TRUNK LID LOCK <i>see Pan</i>	1	\$ 641.06	\$641.06	✓
REAR TRUNK LID LOCK COVER <i>HH</i>	1	\$ 129.80	\$ 129.80	X
REAR TRUNK LID LOCK SWITCH <i>HH</i>	1	\$ 468.90	\$ 468.90	X
REAR TRUNK LID COVER TRIM BOARD <i>HH</i>	1	\$ 303.10	\$303.10	X
REAR TRUNK LID RUBBER <i>Heu</i>	1	\$ 511.28	<i>362.50</i> \$511.28	✓
REAR TRUNK LID LAMP G5 <i>HH Hfs broken</i>	1	\$ 891.52	\$891.52	✓
REAR TRUNK LID GLASS (BLACK COLOR) <i>HH</i>	1	\$ 2,197.58	\$2,197.58	X
BOARD ASSY, BACK DOOR TRIM <i>HH</i>	1	\$ 356.16	\$356.16	X
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>	1	\$ 1,845.58	<i>913.60</i> \$1,845.58	✓
REAR TRUNK LID LOGO (PRIUS) <i>Heu</i>	1	\$ 85.12	\$85.12	✓
REAR TRUNK LID LOGO (HYBRID) <i>Heu</i>	1	\$ 73.36	\$73.36	✓
REAR TRUNK LID LOGO (TOYOTA STAR) <i>Heu</i>	1	\$ 74.06	\$74.06	✓
THIRD BRAKE LIGHT <i>HH</i>	1	\$ 552.58	\$552.58	X
REAR TRUNK LID STRIKER <i>HH</i>	1	\$ 138.18	\$138.18	X
REAR TRUNK LID HINGE (LH/RH) <i>HH</i>	2	\$ 265.30	\$530.60	X
REAR TRUNK LID ABSORBER (LH/RH) <i>HH</i>	2	\$ 402.50	\$805.00	X
REAR TRUNK LID ABSORBER BRACKET (LH/RH) <i>HH</i>	2	\$ 179.06	\$358.12	X
REAR TRUNK LID STOPPER (LH/RH) <i>HH</i>	2	\$ 118.72	\$237.44	X
SPOILERSUB-ASSY, REAR <i>HH</i>	1	\$ 1,335.18	\$1,335.18	X
REAR BUMPER <i>Reuhl</i>	1	\$ 642.04	\$642.04	✓
REAR BUMPER RE-INFORCEMENT <i>Reuhl</i>	1	\$ 446.32	\$446.32	✓
REAR BUMPER UNDER COVER <i>HH</i>	1	\$ 773.64	\$773.64	X
				X

REAR BUMPER UNDER CENTRE COVER <i>HH chisoleph</i>	1	\$ 773.64	\$773.64	✓
REAR BUMPER TOWING COVER <i>HH</i>	1	\$ 115.78	\$115.78	×
REAR BUMPER CLIPS <i>HH HH</i>	1	\$ 30.80	\$30.80	✓
REAR BUMPER SIDE CLIP <i>HH</i>	2	\$ 35.00	\$70.00	×
REAR BUMPER UPPER STOPPER <i>HH</i>	2	\$ 106.96	\$213.92	×
ARM SUB-ASSY, REAR BUMPER, RH <i>HH</i>	1	\$ 195.44	\$195.44	×
REAR BUMPER UNDER SIDE COVER (RH) <i>HH</i>	1	\$ 324.80	\$324.80	×
RETAINER, REAR BUMPER, SIDE, RH <i>HH</i>	1	\$ 132.72	\$132.72	×
RETAINER, REAR BUMPER, UPPER SIDE (LH/RH) <i>HH</i>	2	\$ 42.98	\$85.96	×
RETAINER, REAR BUMPER, SIDE, LH <i>HH</i>	1	\$ 132.72	\$132.72	×
REAR BUMPER UNDER SIDE COVER (LH) <i>HH broken</i>	1	\$ 324.80	\$324.80	×
ARM SUB-ASSY, REAR BUMPER, LH <i>HH</i>	1	\$ 195.44	\$195.44	×
REAR BUMPER LOWER COVER GARNISH G5 <i>Reuhl</i>	1	\$ 963.63	\$963.63	✓
TAIL LAMP ASSY (UPPER) G5 <i>broken H/S o/s HH</i>	2	\$ 942.90	\$1,885.80	✓
TAIL LAMP ASSY (LOWER) G5 <i>HH</i>	2	\$ 860.58	\$1,721.16	×
TAIL LAMP QUARTER PANEL <i>HH</i>	2	\$ 302.40	\$604.80	×
REAR END PANEL GARNISH COVER <i>HH</i>	1	\$ 138.90	\$138.90	×
TAIL LAMP SIDE COVER <i>HH</i>	2	\$ 358.40	\$716.80	×
LAMP ASSY, SIDE TURN SIGNAL, RH <i>HH</i>	1	\$ 91.42	\$91.42	×
LAMP ASSY, SIDE TURN SIGNAL, L H <i>HH</i>	1	\$ 91.42	\$91.42	×
REAR END PANEL <i>Reuhl</i>	1	\$ 842.94	\$842.94	✓
REAR END PANEL GARNISH <i>HH</i>	1	\$ 294.80	\$294.80	×
REAR SPARE TYRE PANEL <i>HH</i>	1	\$ 960.80	\$960.80	×
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE) <i>HH</i>	1	\$ 668.90	\$668.90	✓
REAR FIBER TOOL BOX TRIM <i>HH</i>	1	\$ 557.20	\$557.20	×
SPARE TYRE LOCK NUT <i>HH</i>	1	\$ 123.76	\$123.76	×
REAR EXHAUST PIPE RH <i>HH</i>	1	\$ 1,628.76	\$1,628.76	×
REAR EXHAUST PIPE INSULATOR <i>HH</i>	1	\$ 440.44	\$440.44	✓
REAR FENDER SHIELD (LH/RH) <i>HH</i>	2	\$ 187.88	\$375.76	×
REAR FENDER TRIMBOARD (LH/RH) <i>HH</i>	2	\$ 1,015.00	\$2,030.00	×
REAR WINDSCREEN GLASS W/ MOULDING <i>HH</i>	1	\$ 2,489.62	\$2,489.62	×
SUB TOTAL <i>10,694.87</i>			\$34,512.35	
LESS 20% <i>25%</i> <i>8,021.15</i>			\$6,902.47	

REAR TRUNK LOWER W/S MOULDING <i>HH</i>	SN	1	\$180.00	\$180.00	X
REAR LOWER W/S SEALANT <i>HH</i>	SN	1	\$46.00	\$46.00	✓
REAR NO. PLATE WITH TRIM COVER <i>HH</i>	SN	1	\$ 140.00	\$140.00	X
REAR TRUNK LID APPS STICKER <i>HH</i>	SN	1	\$ 56.00	\$56.00	✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>HH</i>	SN	1	\$ 84.00	\$84.00	✓
REAR BUMPER REVERSE SENSOR <i>DHL</i>	SN	1	\$ 189.98	\$189.98	✓
REAR WINDSCREEN SEALANT <i>HH</i>	SN	1	\$ 46.00	\$46.00	✓
SUB TOTAL				\$741.98	
Labour Charge					
Panel Beating		1	\$ 1,800.00	<i>600/-</i> \$1,800.00	
Spray Painting Charge		1	\$ 1,400.00	<i>600/-</i> \$1,400.00	
Wiring Charge		1	\$ 100.00	<i>30/-</i> \$100.00	
Tuff Kote		1	\$ 100.00	<i>30/-</i> \$100.00	
Towing Charge		1	\$ 80.00	<i>HH</i> \$80.00	
Remove/Refix Cushion & Upholstery Rear		1	\$ 150.00	<i>80/-</i> \$150.00	
Remove/Refix Rear Windscreen Glass		2	\$ 120.00	<i>80/-</i> \$240.00	
Repair Exhaust Pipe		1	\$ 80.00	<i>HH</i> \$80.00	
Diagnostic & Resetting To Erase Fault Code		1	\$ 550.00	<i>HH</i> \$550.00	
TOTAL LABOUR				\$4,500.00	
ESTIMATE TOTAL				\$32,851.86	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

01/10/2024 e 1002m
 Not started
 L/Sum
 7 days
Tyger
 1 km to 1.5

9,863.13

L/S 7,900/-

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer