

BL Automobile Service

25, Kaki Bukit Road 4 #03-33, Synergy@KB Singapore 417800

UEN Reg No: 53394398A

Tel / Hp :

E-Mail: amylia.blgarage@gmail.com

To: Motor Claims Department

Date: 30/09/2024

Vehicle No: VKM680

Model: Yamaha 135LC SE

Estimated Repair Cost For VKM680 (Yamaha 135LC SE)

QTY	Parts	Amount
1	Front mudguard / (MT)	\$ 128.60
1set	Front fork / BT	\$ 480.00
1	Front fork bracket / BT	\$ 126.70
1	Front fork bearing / RC	\$ 115.20
1	Headlamp fairing top / (MT)	\$ 226.70
1set	Headlamp fairing lower / (MT)	\$ 425.60
1	Headlamp assy / (MT)	\$ 325.80
1set	Side fairing / (MT)	\$ 520.00
1	Side fairing inner top garnish o/s / (MT)	\$ 148.20
1	Side signal lamp o/s / (MT)	\$ 175.80
1set	Handle bar grip X	\$ 175.60
1set	Handle bar balancer / (MT)	\$ 155.40
1	Brake level (RH) - GR	\$ 145.20
1set	Wing mirror / GR	\$ 195.00
1	Brake step pedal X	\$ 196.20
1	Side stand X	\$ 176.40
1	Step pedal Bracket/Bar X	\$ 226.50
1set	Front step pedal X	\$ 155.00
1set	Rear side fairing / (MT)	\$ 405.60
1set	Rear side handle bar / (MT)	\$ 175.00
1	Rear exhaust pipe X	\$ 450.20
1set	Rear exhaust heat guard X	\$ 196.80

Parts Sum: \$ 5,325.50

Parts Less 5% : \$ 266.28

Parts Total: \$ 5,059.22

Special Nett Items

1	Front number plate / RC	\$ 20 32.00
1	Rear number plate X RH	\$ 38.00
1set	Supply fairing sticker / RC	\$ 159 280.00

Special Nett Items Total: \$ 350.00

Labour & Misc Charges

Description	Amount
To Remove, Replace, Re-align & Install affected Damaged Areas (\$200.00 per day)	\$ 300 600.00
To Disconnect Wire-Harness to facilitate repairs, Check & Connect Functions	\$ 30 60.00
To Align Body Chassis - Frame	\$ 200.00 X
To Remove Wheel & Balance to Specifications.	\$ 20.00 ✓
Supply Spray Paint Material & Necessary Items To Respray Affected Body & Frame	\$ 200 800.00
Labour Charges Total:	\$ 1,680.00

Parts Total:	\$ 5,059.22
Special Nett Items Total:	\$ 350.00
Labour Charges Total:	\$ 1,680.00
Total Cost Of Repair:	\$ 7,089.22

(Non-Inclusive of GST)

Steve (LKK)
 30/9/24, 11.01 am
 m l
 L/S
 by AL sky
 3 days
 repair limit \$3K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: .

Date: