



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400388
INV Date : 26-08-2024

Reference CD/FCI24060189/Kua3
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SCV 3962C
Insured Veh. SHD 7220U
Claim No. D24005432MFCT
Policy No. D-24101861MFCT
Accident Date 17/06/2024
Inspection Date 03/07/2024

Description	Amount
Survey Inspection	200.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	200.00
GST (9%)	18.00
Grand Total	218.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CD/FCI24060189/Kua3 Date: 26/08/2024 Code: FCI2	
1. Policy Particulars :- DIRECT SETTLEMENT			
Insured Veh.	SHD 7220U	Veh. Inspected	SCV 3962C
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005432MFCT	Excess	\$0.00
Assign From	SERENE LER	Assign Date	21/06/2024
2. Vehicle Details			
Make & Model	SUBARU XV 1.6I-S AWD CVT	C.C	1600
Engine No.	FB16Y596618	Year of Reg.	26/05/2017
Chassis No.	JF1GP3KC5HG205344	Colour	METALLIC PEARL WHITE
Odometer	140011 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORT RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	CONTINENTAL	9
L/H Front Tyre	225/55R17	CONTINENTAL	9
R/H Rear Tyre	225/55R17	CONTINENTAL	9
L/H Rear Tyre	225/55R17	CONTINENTAL	9
4. Description of Damages			
5. General Information			
Accident Date	17/06/2024	Inspection Date	03/07/2024
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SCV 3962C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FENDER ARCH TRIM LH	CUT	\$180.50	\$180.50
	LESS 10.00% DISCOUNT		(\$18.05)	(\$18.05)
			\$162.45	\$162.45

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	COMPUTERISED WHEEL ALIGNMENT	NOT NECESSARY	\$60.00	\$0.00
	TO REPAIR +RESPRAY SPORT RIM LH		\$250.00	\$150.00
	TO KNOCK DENTS ON FRONT FENDER LH AND RENEW PARTS		\$150.00	\$120.00
	TO SPRAY PAINT (INCLUDING FRONT BUMPER/PEARL WHITE)		\$550.00	\$500.00
			\$1,010.00	\$770.00

GRAND TOTAL			\$1,172.45	\$932.45
	RECOMMENDED COST OF REPAIRS			\$932.45

Report Ref No: CD/FCI24060189/Kua3

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 3962C



PHOTOGRAPHS FOR VEHICLE NO. : SCV 3962C





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 3962C





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SCV 3962C

