

來發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

ESTIMATE

EST. No : EST0035083
 Tan Tiong Kheng

Page : 1 of 1
 Your ref : TP-SHD 7220U MS FC
 Job No : 74520
 Our ref : 24.06.22
 Payment :
 Date : 20/6/2024

Attn :

Vehicle No : SCV 3962C
 Vehicle Model : Subaru XV
 Accident on : 17/6/2024

*Not authorized
 Resurvey After Paint
 4 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of parts-Nett item:					
1.00	Pc	Front fender arch trim LH	180.50	10.00	<i>Wt</i> 162.45 ✓
<i>20%</i>					
Labour & Misc:					
1.00		Computerised wheel alignment	60.00		<i>mn</i> 60.00 ✓
1.00		To repair +respray sport rim LH	250.00		250.00 <i>150%</i>
1.00		To knock dents on front fender LH and renew parts	150.00		150.00 <i>120%</i>
1.00		To spray paint (including front bumper / Pearl white)	550.00		550.00 <i>500% 4 days</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
 Signature: _____
 Date: _____

Sub-Total 1,172.45
 GST 9.00% 105.52
 Total **SS** 1,277.97

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."