



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGU 6989P

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER (N)	BENT	\$659.00	\$659.00
1	REAR BUMPER SIDE RETAINER LH (N)	CRACKED	\$22.00	\$22.00
6	REAR BUMPER CLIP @\$5.00 (N)	NECESSARY	\$30.00	\$30.00
1	REAR BOOT (N)	BENT	\$765.00	\$765.00
1	REAR BOOT EMBLEM - ATTRAGE (N)	NECESSARY	\$20.00	\$20.00
1	REAR BOOT LOGO (N)	NECESSARY	\$43.00	\$43.00
1	REAR BOOT INNER LOCK (N)	DENTED	\$195.00	\$195.00
1	REAR BOOT INNER RUBBER (N)	CUT	\$143.00	\$143.00
1	REAR BOOT OUTER CHROME MOULDING (N)	WARPED	\$336.00	\$336.00
1	REAR END PANEL (N)	TO REPAIR SEE LABOUR	\$427.00	\$0.00
1	REAR END PANEL INNER TOP GARNISH (N)	DENTED	\$62.00	\$62.00
	LESS 10.00%		(\$270.20)	(\$227.50)
			\$2,431.80	\$2,047.50

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	DENTED	\$200.00	\$200.00
			\$200.00	\$200.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX REAR BUMPER ASSY, TAILLAMPS, RR BOOT & ATTACHMENT; RENEW REAR PANEL AND RE-ALIGN TO SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL		\$700.00	\$500.00
	TO PUTTY AND RESPRAY ON REAR PANEL BOOT. REAR BUMPER AND OTHER AFFECTED AREAS		\$750.00	\$600.00
	RUSTPROOFING		\$30.00	\$30.00
			\$1,480.00	\$1,130.00

GRAND TOTAL			\$4,111.80	\$3,377.50
--------------------	--	--	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$2,700.00
---	--	--	--	-------------------

Report Ref No: CS/FCI24100002/Kvp3e2				
--------------------------------------	--	--	--	--

MARKET VALUE: \$27,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,937.00=NETT VALUE: \$12,063.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.