



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8TH FLOOR)
MAPLETREE ANSON SINGAPORE 079914

Ref: CS/AWA24100004/Anp3m4

Date: 16/12/2024

Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 9640D	Veh. Inspected	SKM 6413D
Policy No.	BVFCB0015202400	Coverage	0
Claim No.	CSG24VFC1A00023/PC	Excess	\$0.00
Assign From	CHAN PICK YUEN	Assign Date	30/09/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ CLA 200	C.C	1595
Engine No.	27091030350151	Year of Reg.	26/03/2014
Chassis No.	WDD1173432N073645	Colour	BLACK
Odometer	130973 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R18	MATRAX	6
L/H Front Tyre	225/45R18	MATRAX	6
R/H Rear Tyre	225/45R18	MATRAX	6
L/H Rear Tyre	225/45R18	MATRAX	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/09/2024	Inspection Date	30/09/2024
Survey held at	GENUS PERFORMANCE - 39 WOODLANDS CLOSE, #03-03, MEGA@WOODLANDS, SINGAPORE 737856		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days