

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	SOMPO INSURANCE SINGAPORE PL		Ref:	CS3/SMO24100005/Anp3m4	
	50 RAFFLES PLACE #03-03		Date:	23/10/2024	
	SINGAPORE LAND 1	OWER SINGAPORE 048623	Code:	SMO	
1.	1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	FBS 8024E	Veh. Inspected	SJF 61Z	
	Policy No.	-	Coverage	0	
	Claim No.	CMTD2402990/JYC	Excess	\$0.00	
	Assign From	GRACE TEO	Assign Date	30/09/2024	
2. Vehicle Details					
	Make & Model	TOYOTA HARRIER 2.0 PREMIUM	C.C	1986	
	Engine No.	3ZRB655869	Year of Reg.	30/12/2015	
	Chassis No.	ZSU600060169	Colour	BLACK	
	Odometer	177670 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/60R18	BRIDGESTONE	6	
	L/H Front Tyre	225/60R18	BRIDGESTONE	6	
	R/H Rear Tyre	225/60R18	BRIDGESTONE	6	
	L/H Rear Tyre	225/60R18	BRIDGESTONE	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
5.	General Information				
	Accident Date	. ,			
	Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD 15 KAKI BUKIT ROAD 4			
		#01-53 BARTLEY BIZ CENTRE			
_		SINGAPORE 417808			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.					
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.					
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b. Estimate Days of Repair					
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
ESTIMATED NORMAL PERIOD FOR REPAIR. 6 WORKING Days					

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.