

ASS. REC. BY:

REF:

LIP / CS LIP24100007/Knh3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMI=88915 Yr Regn: 06, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q2 715 cc 999

Colour

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

108830

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZGA8JA064570

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

25/9/24

D.O.I.

1/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/10 11:00 @ 2600. Carbur (Red. \$ 6292.60, 70%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 30/09/2024
VEHICLE : SMF8691S
MAKE/MODEL : AUDI Q2
CHASSIS NO : WAUZZZGA6JA064570
MILLAGE : 108830KM
TYRE SIZE :
DOA : 25/09/2024

Not Withain
11 Day & 2600h
Rerun After Rain
3 days

List items

01 PC	REAR BUMPER	1631.40	ms cm	\$ 1,962.00	—
01 PC	REAR BUMPER DISFUFER	613.50	rd 1 ms cm	\$ 1,203.50	—
01 PC	REAR BUMPER INNER BRACKET	219.60	cm	\$ 362.50	✓
02 PC	REAR BUMPER SIDE RETAINER @ \$185.20		sm	\$ 370.40	X
01 PC	REAR BUMPER REFELCTOR LH	36	cm	\$ 211.60	✓
01 PC	REAR END PANEL		n	\$ 1,443.20	X
01 PC	REAR REINFORCEMENT		n	\$ 853.10	X
01 PC	REAR DISFUFER LOWER BRACKET			212.30	
TOTAL PARTS COST			56	\$ 6,618.60	

SPECIAL NETT:

01 PC	PARKING SENSOR	
06 PC	REAR BUMPER CLIP @ \$12.00	
06 PC	REAR BUMPER DISFUFER CLIP @ \$12.00	

1pc	\$ 280.00	X
ms	\$ 72.00	—
ms	\$ 72.00	—
\$ 424.00		

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY DIAGNOSTIC & RESET FAULT CODE TO FACILITATE THE REPAIR

\$ 1,000.00	350l
\$ 600.00	400l
ms \$ 250.00	X
\$ 1,850.00	

TOTAL PARTS

\$ 6,618.60

TOTAL SPECIAL NETT

\$ 424.00

TOTAL LABOUR

\$ 1,850.00

TOTAL COST OF REPAIR

\$ 8,892.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: