



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 30/09/2024
 VEHICLE : SMF8691S
 MAKE/MODEL : AUDI Q2
 CHASSIS NO : WAUZZZGA6JA064570
 MILEAGE : 108830KM
 TYRE SIZE :
 DOA : 25/09/2024

*Not Withain
 11 Day & 2600k
 Resurvey After Rain
 3 days*

List items

01 PC	REAR BUMPER	1631.40	mgcm	\$ 1,962.00	—
01 PC	REAR BUMPER DISFUER	613.50	nd/mgcm	1,203.50	—
01 PC	REAR BUMPER INNER BRACKET	219.60	cm	\$ 362.50	✓
02 PC	REAR BUMPER SIDE RETAINER @ \$185.20		sm	\$ 370.40	X
01 PC	REAR BUMPER REFELCTOR LH	36	cm	\$ 211.60	✓
01 PC	REAR END PANEL		rs	\$ 1,443.20	X
01 PC	REAR REINFORCEMENT		rs	\$ 853.10	X
01 PC	REAR DISFUER LOWER BRACKET			212.30	
TOTAL PARTS COST		56		\$ 6,618.60	

SPECIAL NETT:

01 PC	PARKING SENSOR		sm	\$ 280.00	X
06 PC	REAR BUMPER CLIP @ \$12.00		rs	\$ 72.00	—
06 PC	REAR BUMPER DISFUER CLIP @ \$12.00		rs	\$ 72.00	—
				\$ 424.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$ 1,000.00	350l
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$ 600.00	400l
3. TO SUPPLY DIAGNOTIC & RESET FAULT CODE TO FACILITATE THE REPAIR	\$ 250.00	X
	\$ 1,850.00	

TOTAL PARTS	\$ 6,618.60
TOTAL SPECIAL NETT	\$ 424.00
TOTAL LABOUR	\$ 1,850.00
TOTAL COST OF REPAIR	\$ 8,892.60

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: