



86667775

CHENG AUTO
Bodyworks

CHENG AUTO BODYWORKS

Co. Reg. No. 5331E238X | GST Reg. No. M903721111

5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607

6631 0707 cab@chengauto.com

Cheng Auto Bodyworks Singapore

Date: 30 September 2024

PLP

REPAIR DETAILS	
REFERENCE	
Vehicle Reg. No.	SNQ8996T
Make & Model	HONDA / STEPWAGON SPADA 2.0 E:HEV
Chassis No.	RP81035647
Engine No.	LFA2225657
Registration Date	21/03/2024
TP Vehicle Reg. No.	PC3592H
DOA & Location	28/09/2024 GUL ROAD TOWARDS 50 GUL ROAD

ESTIMATES OF PARTS

No.	Description	Qty	Price
1	TAILLAMP RH <i>bro</i>	1	\$ 1,169.32
2	REAR RH LOWER FENDER <i>X11</i>	1	\$ 1,175.58
3	REAR RH UPPER FENDER <i>repair</i>	1	\$ 1,213.59
4	REAR RH SLIDING DOOR <i>X11</i>	1	\$ 1,586.13
5	REAR RH SIDE QUARTER GLASS <i>X11</i>	1	\$ 704.03
		Sub-Total (S\$)	\$ 5,848.65
		Margin on LN Items 20% (S\$)	\$ 1,169.73
		Total Parts (S\$)	\$ 7,018.37

1169.32
20%
935.45

LABOUR

No.	Description	Price
1	LABOUR	200 \$ 800.00
2	SPRAYPAINTING	\$ 600.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	\$ 100.00
4	REMOVE AND REPLACE WINDOW GLASS / QUARTER GLASS	\$ 120.00
5	GENERAL DIAGNOSTICS TO RESET RECALIBRATE USING ORIGINAL SOFTWARE	\$ 500.00
		Total Labour (S\$) \$ 1,580.00

MISCELLANEOUS ITEMS

No.	Description	Qty	Price
1	SEALANT QUARTER GLASS		\$ 100.00
		Total Miscellaneous Items (S\$)	\$ 100.00

Total Parts (S\$)	\$	7,018.37
Total Labour (S\$)	\$	1,580.00
Total Miscellaneous (S\$)	\$	100.00
Total (S\$)	\$	8,698.37
Add GST @ 9% (S\$)	\$	782.85
Total Amount Payable (S\$)	\$	9,481.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

935.45
530.00
1465.45

Rear
Hp 900/10068
3 days
P/P
01/10/24
Resy after repair