

00E 04/12/2027

Veh No: SLC 3525Y Yr Regn: 05 12 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Price: £1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 2.4 T/Radio: Insured / Std / NI / NA

EngNo: 27R2F6596C

C/No: JTDK B3FU 203089776

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: ————

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of Wistlake

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 6 mm L/Bal. 5 mm

D.O.A. 20/06/2024 D.O.J. 21/06/2024

Survey held at Sturvest Wynd

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

Days Of Repair:

Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

BIFROST AUTO PTE LTD

REPAIR ESTIMATEDATE: 20-Jun-24INSURANCE: IIIMODEL: TOYOTA PRIUS G5VEHICLE NO.: SHC 3525Y

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR BUMPER <i>punctured</i>	1	\$ 642.04	\$642.04
REAR BUMPER SIDE RETAINER <i>HH</i>	1	\$ 157.78	\$157.78
REAR BUMPER CLIPS <i>Hu</i>	1	\$ 30.80	\$30.80
REAR BUMPER SIDE CLIP <i>HH</i>	1	\$ 35.00	\$35.00
RETAINER, REAR BUMPER, SIDE, LH <i>HH</i>	1	\$ 132.72	\$132.72
REAR BUMPER UNDER SIDE COVER (LH) <i>HH</i>	1	\$ 324.80	\$324.80
ARM SUB-ASSY, REAR BUMPER, LH <i>HH</i>	1	\$ 195.44	\$195.44
TAIL LAMP ASSY (UPPER) G5 <i>HH</i>	1	\$ 942.90	\$942.90
TAIL LAMP ASSY (LOWER) G5 <i>HH</i>	1	\$ 860.58	\$860.58
TAIL LAMP QUARTER PANEL <i>HH</i>	1	\$ 302.40	\$302.40
TAIL LAMP SIDE COVER <i>HH</i>	1	\$ 358.40	\$358.40
REAR FIBER TOOL BOX TRIM <i>HH</i>	1	\$ 557.20	\$557.20
REAR FENDER, LH <i>Dented</i>	1	\$ 1,171.38	\$1,171.38
REAR FENDER INNER PANEL, LH <i>HH</i>	1	\$ 1,019.20	\$1,019.20
REAR FENDER OUTER PANEL, LH <i>HH</i>	1	\$ 680.40	\$680.40
REAR FENDER REINFORCEMENT, ROCKER, PANEL, LH <i>HH</i>	1	\$ 773.22	\$773.22
REAR FENDER PANEL, ROOF SIDE OUTER, LH <i>HH</i>	1	\$ 435.40	\$435.40
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, LH <i>HH</i>	1	\$ 371.14	\$371.14
REAR FLOOR PANEL SIDE (LH) <i>HH</i>	1	\$ 386.68	\$386.68
REAR FENDER SIDE PANEL (LH) <i>HH</i>	1	\$ 231.00	\$231.00
REAR FENDER SHIELD (LH) <i>defunct damaged</i>	1	\$ 187.88	\$187.88
REAR FENDER TRIMBOARD (LH) <i>HH</i>	1	\$ 1,015.00	\$1,015.00
REAR FENDER TOP COVER (BLACK COLOR)(LH) <i>HH</i>	1	\$ 421.54	\$421.54
REAR FENDER AIR DUCT <i>HH</i>	1	\$ 231.14	\$231.14

REAR FENDER TOP PANEL INNER HH	1	\$ 476.28	\$476.28
REAR DOOR RUBBR SEAL OUTER SVL	1	\$ 361.06	\$361.06
PANEL SUB-ASSY, REAR DOOR, LH regu	1	\$ 1,761.62	\$1,761.62
REAR DOOR TRIMBOARD HH	1	\$ 1,015.00	\$1,015.00
REAR DOOR INNER LOCK HH	1	\$ 902.58	\$902.58
REAR TYRE (LH) HH	1	\$ 302.40	\$302.40
REAR TYRE RIM (LH) end	1	\$ 2,177.00	\$2,177.00
REAR WHEEL CAP (LH) HF	1	\$ 248.78	\$248.78
REAR WHEEL BEARING & HUB Dnr	1	\$ 854.28	\$854.28
REAR CROSS MEMBER Dendel	1	\$ 3,080.56	\$3,080.56
REAR SHOCK ABSORBER St	1	\$ 165.62	\$165.62
REAR SHOCK ABSORBER MOUNTING HH	1	\$ 175.42	\$175.42
REAR LOWER ARM distorml	1	\$ 696.50	\$696.50
REAR UPPER ARM St	1	\$ 499.52	\$499.52
REAR KNUCKLE ARM distorml	1	\$ 1,134.84	\$1,134.84
REAR BRAKE ABS SENSOR (WIRE) HH	1	\$ 110.32	\$110.32
REAR STABILIZER BAR HH	1	\$ 436.10	\$436.10
REAR STABILIZER LINK HH	1	\$ 212.24	\$212.24
REAR TRAILING ARM distorml	1	\$ 439.88	\$439.88
REAR ASSIST ARM distorml	1	\$ 479.08	\$479.08
FRONT BUMPER COVER G5 distorml	1	\$ 1,322.48	\$1,322.48
FRONT BUMPER REINFORCEMENT HH	1	\$ 974.96	\$974.96
FRONT BUMPER REINFORCEMENT ABSORBER LH/RH HH	2	\$ 161.98	\$323.96
FRONT BUMPER LOWER REINFORCEMENT BRACKET LH/RH HH	2	\$ 462.00	\$924.00
ABSORBER, FRONT BUMPER, LOWER REINFORCEMENT HH	1	\$ 178.78	\$178.78
FRONT BUMPER SPONGE HH	1	\$ 110.32	\$110.32
FRONT BUMPER LOWER GRILLE broken	1	\$ 208.04	\$208.04
FRONT NO. PLATE GARNISH defined	1	\$ 138.60	\$138.60
FRONT BUMPER CLIPS Lhc	1	\$ 30.80	\$30.80
FRONT BUMPER SIDE RETAINER LH/RH HH	2	\$ 107.80	\$215.60
FRONT BUMPER TOP GARNISH HH	1	\$ 315.56	\$315.56
COVER, FRONT BUMPER HOLE, LH/RH SVL	2	\$ 39.73	\$79.46
SUPPORT FR BUMPER, LH HH	1	\$ 114.38	\$114.38
FRONT BUMPER CENTRE FRAME HH	1	\$ 331.66	\$331.66
UNIT ASSY, HEADLAMP, LH/RH (LED) o/s mostly broken w/s HH	2	\$ 4,837.00	\$9,674.00

X
 X
 X
 X
 X
 X
 ✓ 1570.55
 X
 ✓ 610.20
 ✓ 2179.4
 ✓
 X
 ✓ 497.50
 ✓
 ✓ 810.60
 X
 X
 X
 ✓
 ✓
 ✓ 586.18
 X
 X
 X
 X
 X
 ✓
 ✓
 ✓
 X
 X
 X
 X
 X
 X
 ✓
 3325.56

HEAD LAMP PANEL (LH) <i>HH</i>	1	\$	336.14	\$336.14	X
TOP PANEL CENTRE <i>HH</i>	1	\$	510.97	\$510.97	X
TOP PANEL SIDE LH/RH <i>HH</i>	2	\$	204.26	\$408.52	X
BRACE PANEL <i>HH</i>	1	\$	105.28	\$105.28	X
BRACKET, HEADLAMP MOUNTING, LH/RH <i>HH</i>	2	\$	35.70	\$71.40	X
RADIATOR ASSY <i>HH</i>	1	\$	2,578.52	\$2,578.52	X
STAY, RADIATOR SUPPORT, LH <i>HH</i>	1	\$	91.98	\$91.98	X
DEFLECTOR, RADIATOR SIDE, LH <i>HH</i>	1	\$	116.90	\$116.90	X
HORN (1 PC) <i>HH</i>	2	\$	157.79	\$315.59	X
AIR DUCT <i>HH</i>	1	\$	181.16	\$181.16	X
INLET ASSY, AIR CLEANER <i>HH</i>	1	\$	278.88	\$278.88	X
AIR DUCT CENTRE <i>HH</i>	1	\$	131.64	\$131.64	X
CONDENSER ASSY, W/RECEIVER <i>HH</i>	1	\$	1,871.24	\$1,871.24	X
SUB TOTAL				\$48,933.95	
LESS 20% <i>25%</i>				\$9,786.79	
DISCOUNTED TOTAL				\$39,147.16	
REAR BUMPER ADVERTISEMENT <i>Hec</i> SN	1	\$	120.00	\$120.00	✓
REAR BUMPER RUBBER MAT <i>Hec</i> SN	1	\$	70.00	\$70.00	✓
REAR DOOR COMFORT & APPS STICKER <i>Hec</i> SN	1	\$	112.00	\$112.00	✓
REAR DOOR ADVERTISEMENT LOGO <i>Hec</i> SN	1	\$	140.00	\$140.00	✓
FRONT NO. PLATE <i>vt</i> SN	1	\$	35.00	\$35.00	} 45/-
FRONT NO. PLATE TRIM COVER <i>broken</i> SN	1	\$	42.00	\$42.00	
COOLANT <i>HH</i> SN	1	\$	45.00	\$45.00	X
REAR FENDER ADVERTISEMENT LOGO (LH/RH) <i>Hec</i> SN	1	\$	140.00	\$140.00	✓
SUB TOTAL				\$704.00	627.00 =
Labour Charge					
Panel Beating	1	\$	2,600.00	\$2,600.00	800/-
Spray Painting Charge	1	\$	2,000.00	\$2,000.00	800/-
Wiring Charge	1	\$	100.00	\$100.00	HH
Tuff Kote	1	\$	120.00	\$120.00	20/-
Towing Charge	1	\$	80.00	\$80.00	HH
Remove/Refix Cushion & Upholstery Rear	1	\$	150.00	\$150.00	80/-
Remove/Refix Reverse Sensor	1	\$	120.00	\$120.00	40/-

13,573.63

10,180.22

} 45/-

627.00 =

800/-

800/-

HH

20/-

HH

80/-

40/-

Remove/Refix Undercarriage (RR)	1	\$ 400.00	\$400.00
Re-set Rear ABS System	1	\$ 400.00	\$400.00
Remove/Refix Fuel Tank	1	\$ 80.00	\$80.00
Remove/Refix Exhaust Pipe	1	\$ 80.00	\$80.00
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00
Re-set Rear Power Window System	1	\$ 200.00	\$200.00
Four Wheel Alignment	1	\$ 120.00	\$120.00
Remove/Refix Radiator	1	\$ 90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$ 130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00
TOTAL LABOUR			\$7,300.00
ESTIMATE TOTAL			\$47,151.16

150/-

HH

HH

HH

HH

HH

60/-

HH

HH

HH


1950.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

21/06/2024 e 1700hrs


Not Actual

L/S time 8⁹ days.



LKK Auto

Check Part Prices.



12,757.22

Supp 516.60

13,273.82

L/S 11,900/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

SUPPLEMENTARY

DATE: 26/6/24

INSURANCE: III

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHC 3525 Y (S)

DESCRIPTION	QTY	LIST PRICE	AMOUNT
Fuel tank neck <i>punctured</i>	1	\$ 688.80	\$ 688.80
SUB TOTAL			\$ 688.80
LESS 20% <i>25%</i>			\$ 137.76
DISCOUNTED TOTAL			\$ 551.04
ESTIMATE TOTAL			\$ 551.04

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the Insurance company. Please send your book value request to: claims_itr@bifrostauto.com

[Signature]

2KK And

516.60

[Large handwritten mark]

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SHC3525Y
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Jun 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	2ZR2F65966
Chassis No.:	JTDKB3FU203089776
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	05 Dec 2019
First Registration Date:	05 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Dec 2027
PARF Rebate Amount:	\$10,897.00

Intended COE Rebate Details

COE Expiry Date:	04 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$10,959.00
Total Rebate Amount:	\$21,856.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Jun 2024

OK