



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2501365

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:EMILY TAN

INV Date 10/03/2025
Reference CD/FCI24100012/Rua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNR 516T
Insured Veh. SHA 1353A
Claim No. D24008625MFCT
Policy No. D-24101861MFCT
Accident Date 29/09/2024
Inspection Date 18/11/2024

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (9%)	22.50
Grand Total	272.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: EMILY TAN			Ref: CD/FCI24100012/Rua3q2(N) Date: 10/03/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 1353A	Veh. Inspected	SNR 516T
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24008625MFCT	Excess (\$)	0.00
	Assign From	EMILY TAN	Assign Date	18/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	KIA NIRO HYBRID 1.6 SX DCT	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2024
	Chassis No.	KNACT81EVR5180555	Colour	BLUE
	Odometer	61970 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/09/2024	Inspection Date	18/11/2024
	Survey held at	CYCLE & CARRIAGE KIA PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNR 516T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	80.00	20.00
1	COVER -RR BUMPER (SN)	TO REPAIR SEE LABOUR	611.00	-
1	LAMP ASSY -REAR FOG (SN)	SCRATCHED	550.00	550.00
1	COVER -RR BUMPER LWR (SN)	CRACKED	1,802.00	1,802.00
1	GARNISH ASSY -QTR SIDE RH (SN)	NOT NECESSARY	144.00	-
			3,187.00	2,372.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER REPAIR ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF COVER -RR BUMPER.		1,280.00	640.00
	PAINT WORK ON REAR BUMPER ,REAR RHS FENDER .		1,650.00	550.00
	TO REMOVE & REFIT REAR PARKING SENSOR .		240.00	120.00
	TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.		150.00	80.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		380.00	280.00
			3,700.00	1,670.00
	GRAND TOTAL		6,887.00	4,042.00
	RECOMMENDED COST OF REPAIRS			4,042.00

Report Ref No. CD/FCI24100012/Rua3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T




PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T



PHOTOGRAPHS FOR VEHICLE NO. : SNR 516T

