



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tan Seng Tiong	Cust No/Name /Tan Seng Tiong
288E BUKIT BATOK STREET 25	Reg No/Reg Date SNR516T / 24/05/2024
#14-62	Date In/Mileage / 0
LICDO @ BB PRESCHOOL TEAM PTE. L	Chassis No KNACT81EVR5180555
Singapore 654288	Engine No G4LLRS321717
Contact No Mobile: 96358247	Make/Model KIA/NIRO 1.6 A SX SR H005 SR
	Colour/Trim M4B / CCV CHARCOAL

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	30/09/2024/ 18:54	TLL	1210/ Lim Teng Keat	11429
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT					
TP CLAIM CDG					
DOA 29/09/2024					
SUR					
00 REPAIR DAYS					
E PNT88000					
TO REPLACE REAR BUMPER,					
REPAIR ACCIDENT AFFECTED AREA					
E PNT98000					
PAINT WORK ON REAR BUMPER, REAR RHS FENDER					
E PNT88000					
TO REMOVE & REFIT REAR PARKING SENSOR					
A 54900099					
TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					
A 10028901					
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					
M SUNDRY					
SUNDRIES					
M COVER-RR BUMPER	1.00	611.00	00.00		611.00
M LAMP ASSY-REAR FOG	1.00	550.00	00.00		550.00
M COVER-RR BUMPER LWR	1.00	1802.00	00.00		1802.00
M GARNISH ASSY-QTR SIDE, RH	1.00	144.00	00.00		144.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

9% GST on Net 6,887.00 619.83

Total Payable 7,506.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.