

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|----------------------------------|---|
| Tan Seng Tiong | Cust No/Name /Tan Seng Tiong |
| 288E BUKIT BATOK STREET 25 | Reg No/Reg Date SNR516T / 24/05/2024 |
| #14-62 | Date In/Mileage / 0 |
| LICDO @ BB PRESCHOOL TEAM PTE. L | Chassis No KNACT81EVR5180555 |
| Singapore 654288 | Engine No G4LLRS321717 |
| Contact No Mobile: 96358247 | Make/Model KIA/NIRO 1.6 A SX SR H005 SR |
| | Colour/Trim M4B / CCV CHARCOAL |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | |
|--|--------------------------|-------------------|-----|---------------------|------------|-------|---------|
| CSM00087 | Cash | 30/09/2024/ 18:54 | TLL | 1210/ Lim Teng Keat | 11429 | | |
| Description of Goods / Services | | | | Qty | Unit Price | Disc% | Amount |
| Z TEXT | | | | | | | |
| TP CLAIM CDG | | | | | | | |
| DOA 29/09/2024 | | | | | | | |
| SUR | | | | | | | |
| OO REPAIR DAYS | | | | | | | |
| E PNT88000 | | | | | | | 1280.00 |
| TO REPLACE REAR BUMPER, | | | | | | | |
| REPAIR ACCIDENT AFFECTED AREA | | | | | | | |
| E PNT98000 | | | | | | | 1650.00 |
| PAINT WORK ON REAR BUMPER, REAR RHS FENDER | | | | | | | |
| E PNT88000 | | | | | | | 240.00 |
| TO REMOVE& REFIT REAR PARKING SENSOR | | | | | | | |
| A 54900099 | | | | | | | 150.00 |
| TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | | | | | | | |
| A 10028901 | | | | | | | 380.00 |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM | | | | | | | |
| M SUNDRY | | | | | | | 80.00 |
| SUNDRIES | | | | | | | |
| M | COVER-RR BUMPER | | | 1.00 | 611.00 | 00.00 | 611.00 |
| M | LAMP ASSY-REAR FOG | | | 1.00 | 550.00 | 00.00 | 550.00 |
| M | COVER-RR BUMPER LWR | | | 1.00 | 1802.00 | 00.00 | 1802.00 |
| M | GARNISH ASSY-QTR SIDE,RH | | | 1.00 | 144.00 | 00.00 | 144.00 |

Confirm & accepted by

| | | |
|---------------|-----------------|----------|
| 9% GST on | Nett 6887.00 | 6,887.00 |
| | | 619.83 |
| Total Payable | | 7,506.83 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.