



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLX 7628A

Cost Plus				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR FENDER RH (WCP)	BENT	\$1,510.00	\$1,510.00
1	REAR FENDER AIR VENT RH (WCP)	SERVICEABLE	\$45.00	\$0.00
1	REAR BUMPER (WCP)	BUCKLED	\$925.00	\$925.00
1	REAR BUMPER OUTER RETAINER RH (WCP)	DISTORTED	\$60.00	\$60.00
1	THIRD BRAKE LAMP (CRACKED) (WCP) (ADDITIONAL)	NOT CONSISTENT WITH THE IMPACT	\$100.00	\$0.00
1	SET REAR BUMPER PARKING SENSOR HOLDERS (WCP) (ADDITIONAL)	NECESSARY	\$65.00	\$65.00
	<b>COST PLUS 10.00%</b>		\$270.50	\$256.00
			\$2,975.50	\$2,816.00
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	\$30.00	\$30.00
1	SEALANT (SN)	NECESSARY	\$40.00	\$40.00
			\$70.00	\$70.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISMANTLE+REFIX REAR WINDSCREEN		\$160.00	\$120.00
	TO CHECK/CLEAR FAULT CODES AFTER REPAIR		\$120.00	\$120.00
	TO DISMANTLE+REFIX REAR SEAT ASSY, REAR SPEAKER BOARD+REAR FENDER INNER TRIM RH, ETC		\$160.00	\$120.00
	TO CUT+WELD, TO KNOCK DENTS ON REAR FENDER INNER PANEL RH AND RENEW PARTS		\$800.00	\$650.00
	TO SPRAY PAINT		\$800.00	\$600.00
			\$2,040.00	\$1,610.00
<b>GRAND TOTAL</b>			<b>\$5,085.50</b>	<b>\$4,496.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>\$4,496.00</b>
	<b>LESS EXCESS</b>			<b>(\$500.00)</b>
	<b>NETT LIABILITY</b>			<b>\$3,996.00</b>
Report Ref No: CS/UOI24100014/Kvp3m4				



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.