

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035742
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page 1 of 2
Your ref. DHOM110167111905
Job No. 74715
Our ref. 24.09.17
Payment
Date 30/9/2024

Attn

Vehicle No SLX 7628A
Vehicle Model : Volkswagen Passat
Accident on ... 14/9/2024

Not Withheld

Resurvey Bk paint

Ex \$300/ 5 days

\$4496.00

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear fender RH	1,510.00		Bz 1,510.00 ✓
1.00	Pc	Rear fender air vent RH	45.00		Bu 45.00 ✓
1.00	Pc	Rear bumper	925.00		Bu 925.00 ✓
1.00	Pc	Rear bumper outer retainer RH	60.00		DT 60.00 ✓
Total amount of parts supplied-S\$2,540.00					
1.00		10% of parts supplied:	254.00		254.00
Special nett item:					
1.00	Pc	Rear windscreen inner seal	30.00		mc 30.00 ✓
Labour & Misc:					
1.00		To dismantle+refix rear windscreen	160.00		1201 160.00
1.00		To supply sealant	40.00		40.00 ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035742
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page 2 of 2
Your ref. DHOM110167111905
Job No. 74715
Our ref 24.09.17
Payment
Date 30/9/2024

Attn

Vehicle No SLX 7628A
Vehicle Model : Volkswagen Passat
Accident on ... 14/9/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To check/clear fault codes after repair	120.00		120.00 ✓
1.00		To dismantle+refix rear seat assy, rear speaker board+rear fender inner trim RH, etc	160.00		160.00 120
1.00		To cut+weld, to knock dents on rear fender inner panel RH and renew parts	800.00		800.00 650
1.00		To spray paint	800.00		800.00 600

Sub-Total 4,904.00
GST 9.00% 441.36
Total S\$ 5,345.36

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

SUPPLEMENTARY

ESTIMATE

EST. No EST0035742
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page 1 of 1
Your ref. DHOM110167111905
Job No. 74715
Our ref 24.09.17
Payment
Date 21/11/2024

Attn

Vehicle No SLX 7628A
Vehicle Model : Volkswagen Passat
Accident on ... 14/9/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
SUPPLEMENTARY ITEM:					
1.00	Pc	Third brake lamp	(CM) 100.00	N.C	100.00 X
1.00	Set	Rear bumper parking sensor holders	65.00	na	65.00
Total amount of parts supplied-S\$165.00					
1.00		10% of parts supplied:	16.50		16.50

Sub-Total 181.50
GST 9.00% 16.34
Total S\$ 197.84

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."