来發(明記)摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No: EST0035742 146 Robinson Road #02-01 UOI Building

Your ref Job No. .

24.09.17 Payment

Vehicle No ...: SLX 7628A

Vehicle Model: Volkswagen Passat

Accident on 14/9/2024

£4496.11h

NOT Nothern Resorry BEPGIN Ex \$ 300/ 5day

Quantity Unit	Description	Unit price Disc pct	Amount
	Supply of Parts:		
1.00 Pc 1.00 Pc 1.00 Pc 1.00 Pc	Rear fender RH Rear fender air vent RH Rear bumper Rear bumper outer retainer RH	1,510.00 45.00 925.00 60.00	Bu 925.00 Z Bu 925.00 Z Diy 60.00
	Total amount of parts supplied-S\$2,540.00		
1.00	10% of parts supplied:	254.00	254.00
	Special nett item:		
1.00 Pc	Rear windscreen inner seal	30.00	M 30.00 -
	Labour & Misc:		12-4
1.00	To dismantle+refix rear windscreen	160.00	160.00
1.00	To supply sealant	40.00	40.00
		LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during resurvey Parts group are publicable of confirmation	

- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。Acknowledged by Repairer 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發(明記)摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267 GST No: M2-0128609-3 UEN: 199407592C

ESTIMATE

EST. No: EST0035742 United Overseas Insurance Ltd 146 Robinson Road #02-01 UOI Building

Your ref. : DHOM110167111905 24.09.17 Our ref Payment

Vehicle No ...: SLX 7628A

Vehicle Model: Volkswagen Passat

Accident on ...: 14/9/2024

	*		
Quantity Unit	Description	Unit price Disc. pct.	Amount
1.00	To check/clear fault codes after repair	120.00	120.00 $ u$
1.00	To dismantle+refix rear seat assy, rear speaker board+rear fender inner trim RH, etc	160.00	160.00 1201
- 1.00	To cut+weld, to knock dents on rear fender inner panel RH and renew parts	800.00	800.00 634
1.00	To spray paint	800.00	800.00

Sub-Total			4,904.00
GST 9.00%			441.36
Total		S\$	5.345.36

本公司拥有最先进的 CAROLINER MARK IV 机械,可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。 除外,还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."