



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

not Authorized

7 October 2024

REG NO.: SMD 1676 T
MAKE/MODEL: HONDA CITY

all
modules
1/10/24
d/s # 36001
telephone repair
5 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear boot lid	\$ 20/Bent 595.20 ✓
2	Rear boot hinges	\$ 11 128.80 X
1	Rear boot inner trim	\$ 11 179.80 X
2	Rear boot lamps	186.90 N/Snn \$ 0/SSCR 373.80 1PC
1	Rear boot inner lock	\$ 149.60 ✓
1	Rear boot logo	\$ 22.50 ✓
1	Rear boot weatherstrip	\$ 97.90 ✓
1	Rear boot "CITY" emblem	\$ 31.60 ✓
1	Rear boot "VTEC" emblem	\$ 32.70 ✓
1	Rear boot outer chrome moulding	\$ 11 212.50 X
2	Rear boot number plate lamps	\$ 11 64.00 X
2	Rear taillamps	295.60 N/Snn \$ 0/SSCR 591.20 1PC
2	Rear taillamp lower brackets	\$ 37.20 X
1	Rear end panel	466.20 \$ Body 525.50 ✓
1	Rear end panel inner garnish	\$ 135.50 ✓
1	Rear bumper	566.10 \$ De/Born 570.60 ✓
2	Rear bumper brackets	\$ 116.00 X
1	Rear bumper lower grille	\$ 135.00 ✓
2	Rear bumper reflectors	\$ 230.00 X
1	Rear bumper reinforcement	\$ 98.00 X
2	Rear bumper reinforcement covers	\$ 177.20 X
2	Rear bumper side retainers	\$ 97.20 X
4	Rear bumper PDC sensors	188.20 \$ 0/SSCR 740.00 1PC
1	Rear floor panel	\$ 911.40 X
1	Rear bubble sensor	108.20 \$ 146.80 ✓
1	Rear fender	\$ 765.60 X
2	Rear fender inner trims	\$ 393.80 X
		\$ 7,559.40
	Less 20%	\$ 1,511.88
		\$ 6,047.52

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$	60.00	30 s/n
1	Rear number plate with holder	\$	50.00	X
		\$	110.00	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	150.00	60
3	To remove and refit rear reverse sensor.	\$	180.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	50
5	To apply undercoating.	\$	200.00	60
6	Panel beating.	\$	1,600.00	850
7	To re-spray painting on the affected areas.	\$	1,500.00	1000
		\$	3,830.00	

GRAND TOTAL :**\$ 9,987.52**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 3008
202
2406.40
30
2070
45064
202
3605