

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 081026001

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE SJP940J

Not Authorized
U.Sig &

Survey After Repair

No.	Qty	List Items	
1	1	Rear bumper	\$ Bu 451.60 ✓
2	2	Rear bumper side reflector	\$ Bu 185.80 X
3	2	Rear bumper inner side bracket	\$ 112.60 ?
4	2	Rear bumper side retainer	\$ Bu 171.20 X
5	2	Rear bumper corner retainer	\$ Bu 86.00 X
6	1 set	Rear bumper clips	\$ Bu 40.00 ✓
7	1	Rear boot lid	\$ Bu 589.10 ✓
8	1	Rear boot centre "TOYOTA" logo	\$ Bu 48.10 —
9	1	Rear boot LH "VIOS" emblem	\$ Bu 55.60 —
10	1	Rear boot RH "E" emblem	\$ Bu 45.30 —
11	1	Rear boot top lock	\$ Bu 121.35 —
12	1	Rear boot lower lock catch	\$ Bu 41.40 X
13	1	Rear boot weatherstrip	\$ 176.80 ?
14	2	Taillamp	\$ CM 665.20 ✓
15	1	Rear end panel	\$ 575.00 ?
16	1	Rear end panel top garnish	\$ Bu 211.40 ✓
			\$ 3,576.45
Less 25%			\$ 894.11
Total :			\$ 2,682.34

Special Nett Items

17	1 set	Reverse sensors	\$ Bu 280.00 X
18	1 set	Rear end panel sealant	\$ 60.00 ?
Total :			\$ 340.00

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,000.00 ?
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 600
3	To check wirings and lightings.	\$ 40.00 20
4	To remove, refit reverse sensors.	\$ 70.00 50
5	To remove, refit rear boot lid fittings.	\$ 80.00 50
6	To remove, refit rear upholstery and attachments.	\$ 150.00 ?
7	To supply and apply anti rust treatment	\$ 80.00 ?
Total :		\$ 2,420.00

Total Parts and Labour : \$ 5,442.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer