



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100020/Knp3m4
16 RAFFLES QUAY	Date:	09/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 6262R	Veh. Inspected	SHF 612H
Policy No.	-	Coverage	0
Claim No.	D24008626MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	01/10/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)	C.C	1798
Engine No.	2ZR2J09325	Year of Reg.	26/02/2021
Chassis No.	JTDKB3FU703093855	Colour	METALLIC PEARL WHITE / RED
Odometer	356412 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WANLI	7
L/H Front Tyre	195/65R15	WANLI	7
R/H Rear Tyre	195/65R15	WANLI	7
L/H Rear Tyre	195/65R15	WANLI	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/03/2024	Inspection Date	01/10/2024
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days