

ASS. REC. BY:

REF:

F67/ CS/F124100020/Knp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHF 612H

Yr Regn:

02, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Pro

C.C.

1798

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

358412

T/Radio:

Insured / Std / NI / NA

Eng/No:

Metallic Pearl White/ Red

C/No:

JTDKB3FU703093855

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Wanli

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

13/3/24

D.O.I.

1/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3/10/24 11:50pm @ 1050p. Contact (Red. \$ 8509.40, 89%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHF612H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Mar 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2J09325
Chassis No.:	JTDKB3FU703093855
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,879.00
Original Registration Date:	26 Feb 2021
First Registration Date:	26 Feb 2021
Transfer Count:	0
Actual ARF Paid:	\$7,131.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2029
PARF Rebate Amount:	\$5,348.00

Intended COE Rebate Details

COE Expiry Date:	25 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$31,876.00
COE Rebate Amount:	\$19,720.00
Total Rebate Amount:	\$25,068.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Mar 2024

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHF612H**AAD2403-059***Not Authorised
61 Rmp @ 1050/-*

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

01 OCT 2021**SHF612H****JTDKB3FU703093855****200303878K****TOYOTA****PRIUS GEN 4****13/3/2024****SHB6262R/FCI****26/2/2021****PART****LIST**

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

\$	Bu	612.68	✓
\$	bu	27.93	X
\$	cm	472.19	✓
\$	bu	167.48	X
\$	bu	167.48	X
\$	bu	419.90	X
\$	bu	49.25	X
\$	bu	49.25	X
\$	bu	220.50	X
\$	bu	304.92	X
\$	bu	290.43	X
\$	bu	159.39	X
\$	bu	824.46	X

TOTAL \$ 3,765.86**25% \$ 941.47****\$ 2,824.40****SPECIAL NETT**

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	bu	700.00	X
\$	bu	65.00	bu
\$	bu	60.00	X
\$	NSP	180.00	X
\$	bu	150.00	X
\$	bu	200.00	X
\$	bu	130.00	X

TOTAL \$ 1,485.00**TOTAL PARTS \$ 4,309.40****LABOUR**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHF612H**AAD2403-059**

To rust-proofing of the affected areas.	\$	na	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2001
To transfer of tailgate fittings and conduct water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	~	170.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	~	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501

To check steering geometry and computer wheel alignment	\$	~	220.00	X
TOTAL	\$		5,250.00	

OVERALL TOTAL	\$		9,559.40	
----------------------	-----------	--	-----------------	--

2201

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: