

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHF612H****AAD2403-059***Not Authorised  
C/Rump @ 1050/h*

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SHF612H

JTDKB3FU703093855

200303878K

TOYOTA

PRIUS GEN 4

13/3/2024

SHB6262R/FCI

26/2/2021

**01 OCT 2021****PART**

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

**LIST**

\$	Bu	612.68	✓
\$	Ln	27.93	X
\$	cm	472.19	✓
\$	Ln	167.48	X
\$	Ln	167.48	X
\$	Ln	419.90	X
\$	Ln	49.25	X
\$	Ln	49.25	X
\$	Ln	220.50	X
\$	Ln	304.92	X
\$	Ln	290.43	X
\$	Ln	159.39	X
\$	Ln	824.46	X

**TOTAL \$ 3,765.86****25% \$ 941.47****\$ 2,824.40****SPECIAL NETT**

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	Ln	700.00	X
\$	Ln	65.00	✓
\$	Ln	60.00	X
\$	NSP	180.00	X
\$	Ln	150.00	X
\$	Ln	200.00	X
\$	Ln	130.00	X

**TOTAL \$ 1,485.00****TOTAL PARTS \$ 4,309.40****LABOUR**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

**SHF612H****AAD2403-059**

To rust-proofing of the affected areas.	\$	na	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	2201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	2001
To transfer of tailgate fittings and conduct water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	~	170.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	~	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501

To check steering geometry and computer wheel alignment	\$	~	220.00	X
<b>TOTAL</b>	<b>\$</b>		<b>5,250.00</b>	
<b>OVERALL TOTAL</b>	<b>\$</b>		<b>9,559.40</b>	

2201

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: