

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
LOW
KAI HUA, CHARLES
(LIU KAIHUA, CHARLES ALDWIN)
BLK 3 SIN MING WALK
#15-28
SINGAPORE 575575

Document no.
Document date 20-06-2024
Customer no. 6151041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2024016554/ 1
Job order date 20-06-2024
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SNF3833X	NX56QDR0	24-05-2022	TMBKU8NX9NY064130	OCT.COM RS TS180/2.0A7F	20,479

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT/HARNES				#8	280.00	305.20
	REPAIR						
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#8	480.00	523.20
9801B001	CHANGE LANE ASSIST SYSTEM				#8	840.00	915.60
	CALIBRATION						
5E3853687N 041	Inscriptio	1	pcs.	81.50	#8	81.50	88.84
	NAME PLATE - SKODA						
5E3853687P 041	Inscriptio	1	pcs.	81.50	#8	81.50	88.84
	NAME PLATE - OCTAVIA						
5E3853687S XPC	Inscriptio	1	pcs.	81.50	#8	81.50	88.84
	NAME PLATE - VRS						
5E7807421M	Cover For	1	pcs.	2,026.20	#8	2,026.20	2,208.56
5E7919485H	Sensor Bra	1	pcs.	17.02	#8	17.02	18.55
5E7919485G	Sensor Bra	1	pcs.	17.02	#8	17.02	18.55
5E7919486G	Sensor Bra	1	pcs.	17.02	#8	17.02	18.55
5E7919486H	Sensor Bra	1	pcs.	17.02	#8	17.02	18.55
5E7807521E F9R	Spoiler	1	pcs.	486.00	#8	486.00	529.74
5E7807363	Bracket	1	pcs.	77.27	#8	77.27	84.22
	EXH.TAIL PIPE BRACKET LH						
5E3253681D	Exh.Tail P	1	pcs.	739.33	#8	739.33	805.87
5E0945104B	Reflector	1	pcs.	60.86	#8	60.86	66.34
	REFLECTOR (CTR)						
5E6945105	Reflector	1	pcs.	61.29	#8	61.29	66.81
	REFLECTOR (LH)						
5E3807305D	Reinforcem	1	pcs.	690.41	#8	690.41	752.55
5E7807863	Retaining	1	pcs.	84.27	#8	84.27	91.85
	BUMPER CTR BRACKET						
5E7807385	End Plate	1	pcs.	80.12	#8	80.12	87.33
	BUMPER UPPER CLOSING ELEMENT						
5E7807377	Guide Piec		pcs.	65.99	#8	65.99	71.93
	LHR BUMPER BRACKET (UPPER)						
5E7807378	Guide Piec	1	pcs.	65.99	#8	65.99	71.93
	RHR BUMPER BRACKET (UPPER)						
5E7807393	Guide Piec	1	pcs.	52.83	#8	52.83	57.58
	LHR BUMPER BRACKET (SIDE)						
5E7807394	Guide Profile RHS	1	pcs.	52.83	#8	52.83	57.58
	RHR BUMPER BRACKET (SIDE)						
5E3945207A	Taillight	1	pcs.	1,151.80	#8	1,151.80	1,255.46
	LHS TAILLIGHT OUTER						
5E7945427	Trim For T	1	pcs.	21.83	#8	21.83	23.79
	LHS TAILLIGHT TRIM COVER						
2Q0907685E	Control Unit For Lane Cha	1	pcs.	1,953.41	#8	1,953.41	2,129.22
	BLIND SPOT CONTROL UNIT LH						

SKODA Centre Singapore

26 Leng Kee Rd
Singapore 159104
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
Ms First Capital Insurance
Limited
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Mr
LOW
KAI HUA, CHARLES
(LIU KAIHUA, CHARLES ALDWIN)
BLK 3 SIN MING WALK
#15-28
SINGAPORE 575575

Document no.
Document date 20-06-2024
Customer no. 6151041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2024016554/ 1
Job order date 20-06-2024
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SNF3833X	NX56QDR0	24-05-2022	TMBKU8NX9NY064130	OCT.COM RS TS180/2.0A7F	20,479

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5E7907455	Bracket LHS BLIND SPOT CONTROL UNIT BRACKET	1	pcs.	22.68	#8	22.68	24.72
	LABOUR	4	pcs.	840.00	#8	3,360.00	3,662.40
	SPRAY PAINT	4	pcs.	800.00	#8	3,200.00	3,488.00
	MS FIRST CAPITAL DIRECT DOA: 20/6/2024 TP VEH: SHC2302E SURVEY BY:						

Quotation valid till 27-06-2024

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#8	1,600.00	14,565.69	9%	1,454.91	16,165.69	17,620.60
Total	1,600.00	14,565.69		1,454.91	16,165.69	17,620.60

REAR Bumper, TAILGATE & LHR FENDER

Customer

Service Advisor

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

All invoices are denominated in SGD, unless otherwise stated

Signature:

Rane
hp 90010068
5 days
26/06/24
Rane 54
paint