

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURAN	NCE PTE LTD	Ref:	CS/LIP24100023/Rnh3e2(N)	
	ONE RAFFLES QU NORTH TOWER S	JAY #25-01 INGAPORE 048583	Date:	21/01/2025	
	ATTN: SAM LOW		Code	: LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SML 2834E	Veh. Inspected	SLV 2731C	
	Policy No.	SI24V05573/VPC/R02	Coverage (\$)	0.00	
	Claim No.	IVS24/1292	Excess (\$)	0.00	
	Assign From	SAM LOW	Assign Date	01/10/2024	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 520I	c.c	1998	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	WBAJA120X0BJ18501	Colour	GREY	
	Odometer	110809 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/45 R18	PIRELLI	6 mm	
	L/H Front Tyre	245/45 R18	PIRELLI	6 mm	
	R/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
	L/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
4. Description of Damages					
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	5. General Information				
	Accident Date	02/07/2024	Inspection Date	01/10/2024	
	Survey held at	PRESTIGE MOTOR PTE LTD			
		648 DUNEARN ROAD SINGAPORE 289629			
		SINGAPORE 209029			
F		Da	, ma a wl ca		
5a.	Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
<u></u>	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				