



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100025/Unp3m4
16 RAFFLES QUAY	Date:	18/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3255B	Veh. Inspected	SLM 6062X
Policy No.	-	Coverage	0
Claim No.	D24008648MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	01/10/2024

### 2. Vehicle Details

Make & Model	HONDA FREED HYBRID 1.5G AUTO	C.C	1496
Engine No.	LEB5536792	Year of Reg.	03/04/2017
Chassis No.	GB71013809	Colour	WHITE
Odometer	312440 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/65R15	YOKOHAMA	6
L/H Front Tyre	185/65R15	YOKOHAMA	6
R/H Rear Tyre	185/65R15	YOKOHAMA	6
L/H Rear Tyre	185/65R15	YOKOHAMA	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	01/10/2024	Inspection Date	02/10/2024
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days