

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Approved
for
works
2/10/24
3 days
4/s @ 4200
Chaplin Att. 127

VEHICLE No: SLM 6062X

1PC	BONNET	897.20	11	\$1,410.00 X
1PC	FRONT BUMPER		2e/20	\$920.00
1PC	FRONT BUMPER LOWER CENTRE GRILLE		11	\$105.00
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00		11	\$290.00 X
1PC	FRONT BUMPER UNDER COVER		11	\$390.00 X
1PC	FRONT BUMPER REINFORCEMENT	382.90	But	\$920.00
1PC	FRONT BUMPER TOP CENTRE GRILLE		NS	\$280.00 X
1PC	FRONT BUMPER TOW COVER		11	\$30.00 X
1SET	FRONT BUMPER CLIPS		11	\$50.00
1PC	FRONT GRILLE	825.50	one	\$860.00
1PC	FRONT GRILLE OUTER GARNISH		NS	\$445.00 X
1PC	FRONT GRILLE 'H' LOGO		11	\$35.00 X
2PCS	HEADLAMPS @\$2120.00	1 679.90 x 2 = 3359.80	one	\$4,240.00
2PCS	HEADLAMP LOWER BRACKETS @\$180.00		11	\$360.00 X
1PC	FRONT SUPPORT PANEL		11	\$615.00 X
1PC	FRONT SUPPORT PANEL TOP GARNISH		11	\$218.00 X
1PC	AIR CON CONDENSER		11	\$1,400.00 X
1PC	RADIATOR		11	\$1,880.00 X
				\$14,448.00

S.NETT

1SET	BONNET INSULATOR CLIPS	11	\$30.00 X
1PC	FRONT LICENCE PLATE	one	\$50.00 40 s/n
1BOL	RADIATOR COOLANT	11	\$50.00 X
1BOL	AIR CON OIL	11	\$50.00 X

TO CHECK WIRING
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00 20
11	\$100.00 X
11	\$120.00 X
	\$1,000.00 300
	\$1,000.00 400
TOTAL	\$16,898.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 5620.40
202
4496.32
40
720
5258.32
202
4205