

ASSIGNMENT

COE 17 June 2010

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop in/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 5 days Res.: Yes or NoLump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 852 1771 Yr Regn: 18 June 2010Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus IS250 CC: 2500Colour: Black A/C: Insured / Std / NI / NASp. Reading: 263626 T/Radio: Insured / Std / NI / NAEng No: 4GR0667683C/No: JTHBK262705124033

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUNE /

TOYO / YOKO or Bridgestone

Front

Rear

R/Bal: 5 mmR/Bal: 5 mmL/Bal: 5 mmL/Bal: 5 mmD.O.A: 27/09/2024D.O.A: 01/10/2024Survey held at Alfred Auto AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflap or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Income SDF 8877 E
	MV 66K
	ITA 19K
09/10/24	Income 2/5 7,200/- with 5 days reg (Red \$18367, 72%)

Date/Time, File Pass to?

1) 09/10/24

: Prel. Report

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Other

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)Report Format: TPLump Sum / L.R. (\$ 7200)




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No.: 280924

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 28.09.2024

Vista Chia Aik Key

315C Yishun Ave 9 #15-180

Singapore 763315

Lexus IS250 Auto Lux FL

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Repair Cost for Vehicle Reg. No: SJZ 177 T

1 Pc. Rear Boot	Dentel	698.80	✓
1 Pc. Rear Boot Spoiler	HN	1,090.00	X
1 Pc. Rear Boot Logo	HN	159.50	✓ 105.00
1 Pc. Rear Boot IS250 Emblem	HF	85.00	X
2 Pcs. Rear Boot Lamp	H/S minty crack o/s HN @ 430.00	860.00	✓
1 2 Pcs. Rear Boot No. Plate Garnish	CRACK	1,480.90	✓ 697.30
2 Pcs. Rear Boot Np. Plate Lamp	HN @ 201.40	402.80	X
1 Pc. Rear Boot Lock Assy.	DAN	782.00	✓ 423.40
2 Pcs. Rear Lamp LH/RH	H/S minty crack o/s HN @ 636.30	1,272.60	✓ 496.70
1 Pc. Rear Fender	rep H/S	1,090.60	X
1 Pc. Rear Windscreen Moulding	HN	209.50	X
1 Pc. Rear Windscreen Seal	HN	80.00	X
1 PC. Rear Windscreen Repair Kit & Sealant	HN	280.00	X
1 Pc. Rear Bumper	Dentel	991.00	✓ 890.00
2 Pcs. Rear Bumper Side Retainer	HN @ 130.00	260.00	X
2 Pcs. Rear Bumper Corner Holder	HN @ 155.30	310.60	X
1 Pc. Rear Bumper Sponge	tom	199.00	✓
1 Pc. Rear Bumper Reinforcement	Dentel	785.50	✓
2 Pcs. Rear Bumper Bracket	Dentel @ 303.80	607.60	✓
4 PCs. Rear Bumper Parking Sensor	DAN @ 529.40	2,117.60	✓ 204.05 x 4 = 816.20
4 Pcs. Rear Bumper Sensor Ring	HN @ 30.00	120.00	✓ 60/-
4 Pcs. Rear Bumper Sensor Holder	HN @ 69.10	276.40	✓
10 Pcs. Rear Bumper Clips	HN @ 8.00	80.00	20/- SH
1 Pc. Rear End Panel	Dentel	799.10	✓
1 Pc. Rear End Panel Centre Holder	HN	221.50	X
1 Pc. Rear End Panel Garnish Board	broken	698.00	✓ 433.60
1 Pc. Rear End Spare Tyre Board	SVC	757.10	X
1 Pc. Rear End Panel Lock Catch	rep	210.00	X
2 Pcs. Rear Fender Top Garnish	HN	681.40	X
1 Pc. Rear Fender Inner Garnish	SVC	1,069.30	X
10 Pcs. Rear Fender Garnish Clips	HN @ 8.00	80.00	X




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



1 Pc. Rear Exhaust	HH		1,840.00	X
2 Pcs. Rear Exhaust Chrome	HH	@ 323.50	647.00	X
1 Pc. Rear Weather Slip	defined		299.80	✓
1 Pc. Rear No. Plate & Box	HH		80.00	X

Total (Panels / Parts): 21,627.00 (SGD)

List 8,018.40

SH 20.00

10% 7,216.56

LABOR CHARGES

To install rear spoiler	150.00	20/-
To remove & refit interior carpet, cushion side board, Garnish & all accident affect area.	280.00	80/-
To remove wiring & check all lighting & wiring & sensor.	200.00	30/-
To remove & refit windscreen.	180.00	HH
To wash interior & dry up all carpet & interior.	180.00	HH
To knocking, straightening, repair & renew all accident Affected area.	1,300.00	800/-
To respray painting on all accident affected area.	1,500.00	800/-
To rust proof all accident affected area.	150.00	30/-

1760.00

Total (Labor Charges): 3,940.00 (SGD)

01/10/2024 e 1630w

Not defined

2/5m 5 days.

TOTAL COST SUMMARY

PANELS / PARTS
LABOR CHARGES

21,627.00
3,940.00

8996.56

2/5/2024

7,200/-

Grand Total: 25,567.00 (SGD)



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

Payment Method

1. PAYNOW via UEN 39108900E
2. Bank Wire Transfer - (SGD Account)

Beneficiary/Company Name	Alfred Auto Services & Supplies
UEN no.	39108900E
Beneficiary's Bank Name	OCBC Bank
Account No.	620-453233-001
Bank Code	7339
Branch Code	620
Swift Code	OCBCSGSG

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.