

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	30-09-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
VEHICLE DETAILS	
VEHICLE NO:	SMR439U
MAKE & MODEL:	TOYOTA PRIUS ALPHA <i>Z4W 40</i>
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	28 September, 2024
TIME:	1705HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,550.30	\$ <u>1,550.30</u>
2	TAILGATE LOGO <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAILGATE EMBLEM PRIUS <i>new</i>	1	\$ 85.00	\$ 85.00
4	TAILGATE EMBLEM HYBRID <i>new</i>	1	\$ 80.00	\$ 80.00
5	TAILGATE HINGE <i>2pc</i>	2	\$ 75.00	\$ 150.00
6	TAILGATE DAMPER <i>new</i>	2	\$ 280.00	\$ 560.00
7	TAILGATE LOCK <i>2nd</i>	1	\$ 365.00	\$ 365.00
8	TAILGATE INNER TRIM BOARD <i>2nd</i>	1	\$ 550.00	\$ 550.00
9	TAILGATE INNER HANDLE <i>new</i>	1	\$ 110.00	\$ 110.00
10	TAILGATE WEATHERSTRIP <i>2nd</i>	1	\$ 320.00	\$ 320.00
11	TAILGATE ANTENNA <i>new</i>	1	\$ 210.00	\$ 210.00
12	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 180.00	\$ 180.00
13	NUMBER PLATE LAMP GARNISH <i>2nd</i>	1	\$ 480.00	\$ 480.00
14	NUMBER PLATE LAMP(SET) <i>new</i>	1	\$ 190.00	\$ 190.00
15	REAR BUMPER <i>2nd</i>	1	\$ 850.50	\$ <u>850.50</u>
16	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 64.20	\$ 128.40
17	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 90.00	\$ 180.00
18	TAILLAMP <i>2nd</i>	2	\$ 630.00	\$ <u>1,260.00</u>
19	REAR FENDER INNER TRIM <i>new</i>	2	\$ 890.00	\$ 1,780.00
20	REAR END PANEL <i>Dented</i>	1	\$ 680.00	\$ 680.00
21	REAR END PANEL TOP GARNISH <i>2nd</i>	1	\$ 260.50	\$ 260.50

22	REAR FLOOR PANEL <i>new</i>	1	\$ 1,055.90	\$ 1,055.90	+
23	REAR FLOOR PANEL CENTRE TRAY <i>new</i>	1	\$ 630.00	\$ 630.00	+
24	REAR FLOOR PANEL CENTRE TRAY COVER <i>new</i>	1	\$ 550.00	\$ 550.00	+

TOTAL PRICE \$ 12,285.60

LESS 25% \$ 3,071.40

SUB TOTAL PRICE \$ 9,214.20

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE	
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00	+
2	TAILGATE INNER TRIM BOARD CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
3	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	60
4	NUMBER PLATE LAMP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
5	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
6	TAILLAMP CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
7	REAR FENDER INNER TRIM CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	+
8	REAR END PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00	60
9	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00	✓
10	REAR FLOOR PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
11	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00	+
12	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	200

TOTAL \$ 1,330.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,000.00	\$ 2,000.00	80
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,000.00	\$ 2,000.00	80
3	TUFF COAT	1	\$ 200.00	\$ 200.00	60
4	WIRING CHECK	1	\$ 80.00	\$ 80.00	30
5	REMOVE AND REFIX REAR WINDSCREEM	1	\$ 140.00	\$ 140.00	120
6	REMOVE AND REFIX REAR TAILGATE MECHANISM	1	\$ 100.00	\$ 100.00	60
7	REMOVE AND REFIX REAR REVERSE CAMERA AND SETTING	1	\$ 80.00	\$ 80.00	50
8	REMOVE AND REFIX REAR REVERSE SENSOR AND SETTING	1	\$ 80.00	\$ 80.00	50

TOTAL \$ 4,680.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	10,544.20
TOTAL LABOUR COST	\$	4,680.00
TOTAL REPAIR COST	\$	15,224.20

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adrian G
2/s 01/10/24
06 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: