

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373

Reg. No: 201538764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	30-09-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
VEHICLE DETAILS	
VEHICLE NO:	SLD7122Y
MAKE & MODEL:	HYUNDAI ELANTRA 1.6
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	30-09-20214
TIME:	0815HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BOOTLID <i>Dented</i>	1	\$ 1,755.20	\$ 1,755.20	✓
2	BOOTLID LOGO <i>to new</i>	1	\$ 80.00	\$ 80.00	✓ 46
3	BOOTLID ELANTRA EMBLEM	1	\$ 80.00	\$ 80.00	✓ 50
4	BOOTLID GLS EMBLEM	1	\$ 80.00	\$ 80.00	✓ 48
5	BOOTLID HINGE <i>new</i>	2	\$ 110.00	\$ 220.00	+
6	BOOTLID LOCK <i>Damaged</i>	1	\$ 190.00	\$ 190.00	✓
7	BOOTLID WEATHERSTRIP <i>cut</i>	1	\$ 120.00	\$ 120.00	✓
8	BOOTLID LAMP <i>new</i>	2	\$ 280.00	\$ 560.00	+
9	BOOTLID ANTENNA SWITCH <i>new</i>	1	\$ 155.00	\$ 155.00	+
10	REAR BUMPER <i>Delend</i>	1	\$ 860.00	\$ 860.00	✓ 474
11	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80	+
12	REAR BUMPER LOWER SPOILER <i>Delend</i>	1	\$ 480.00	\$ 480.00	✓ 355
13	REAR BUMPER REFLECTOR <i>LH cut</i>	2	\$ 90.00	\$ 180.00	✓ 90
14	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 420.00	\$ 420.00	✓ 350
15	REAR BUMPER REINFORCEMENT INNER HOLDER <i>new</i>	2	\$ 30.00	\$ 60.00	+
16	TAILLAMP <i>LH cut</i>	2	\$ 420.00	\$ 840.00	✓ 420
17	REAR END PANEL <i>Dented</i>	1	\$ 580.00	\$ 580.00	✓
18	REAR END PANEL TOP GARNISH <i>Delend</i>	1	\$ 144.20	\$ 144.20	✓
19	REAR FLOOR PANEL <i>new</i>	1	\$ 1,050.00	\$ 1,050.00	+
20	REAR FLOOR PANEL TOP BAORD <i>new</i>	1	\$ 320.00	\$ 320.00	+

TOTAL PRICE \$ 8,299.20

LESS 20% \$ 1,659.84

SUB TOTAL PRICE \$ 6,639.36

3753.92

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE new Bent	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS SET new	1	\$ 22.00	\$ 22.00
3	REAR END PANEL TOP GARNISH CLIPS SET new	1	\$ 20.00	\$ 20.00
4	REAR END PANEL INSULATION SEALANT new	1	\$ 120.00	\$ 120.00
5	REVERSE SENSOR new Dmd	1	\$ 220.00	\$ 220.00
TOTAL				\$ 432.00

30
-
-
60
40
72

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,600.00	\$ 1,600.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,600.00	\$ 1,600.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 250.00	\$ 250.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
8	TRANSFER TBOOTLID MECHANISM	1	\$ 100.00	\$ 100.00

700
60
60
30
60
50
30
60

TOTAL \$ 4,030.00 1610

ESTIMATE REPORT

TOTAL PARTS COST	\$	7,071.36
TOTAL LABOUR COST	\$	4,030.00
TOTAL REPAIR COST	\$	11,101.36

Adrian Li
2/5 01/10/24
06 Days

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3753.92
+ 332.00
+ 1610.00

5695.92
-20% 1139.184

6556.736
Lump sum 6 days

L/S \$4500