

Date: 27/9/2024
Vehicle No: SNP1934Z
Model: TOYOTA ALPHARD
Chassis: JTNACAAH108001158
Reg.Year: 2024

Not Authorised
Repair B4 pain
5 days

Third Party Insurer: CTP
Third Party Veh No: GBK5804H
Date of Accident: 27/9/2024
Estimator: JONATHAN
Surveyor:

14226-85

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOT <i>2911</i>			\$ <i>By</i> 3,236.00 ✓
	RR W/SCREEN MOLDING			\$ <i>Ma</i> 170.00 ✓
	RR BOOTLID EMBLEM (HEV)			\$ <i>Ma</i> 101.00 ✓
	RR BOOTLID INNER TRIM BOARD <i>1621-60</i>			\$ <i>Ma</i> 1,860.00 ✓
	RR BOOTLID LOCK ASSY			\$ <i>Ma</i> 1,108.00 ✓
	RR BOOTLID ELECTRIC STRUT - LH & RH	2	\$ 1,605.00	\$ <i>Ma</i> 3,210.00 ✓
	RR BOOTLID SENSOR ASSY - RH & LH <i>Ma</i>	2	\$ 1,220.00	\$ 2,440.00 ✓
	RR BOOTLID HINGE - LH & RH	2	\$ 93.00	\$ <i>Ma</i> 186.00 X
	RR WEATHERSTRIP			\$ <i>Dis in</i> 481.00 ✓
	RR BUMPER <i>866</i>			\$ <i>Ma</i> 916.00 ✓
	RR BUMPER ULTRASONIC SENSOR - CTR LH & RH <i>C431-80</i>	2	\$ 495.00	\$ <i>Shan</i> 990.00 ✓
	RR END PANEL <i>1601-90</i>			\$ <i>By</i> 2,051.00 ✓
	RR END FLOOR PANEL			\$ <i>Ma</i> 2,505.00 X
	RR END FLOOR TOP COVER - RH			\$ <i>Shan</i> 870.00 X
	RR END PANEL BTM TRIM PANEL			\$ <i>Ma</i> 207.00 ✓
SUB TOTAL				\$ 20,331.00
Less 25%				-\$ 5,082.75
PARTS TOTAL				\$ 15,248.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR END PANEL TOP GARNISH - AFTERMARKET			\$ <i>Shan</i> 110.00 X
	RR W/SCREEN SEALANT			\$ <i>Ma</i> 120.00 ✓
	RR BUMPER LOWER CHROME STRIPS - 1 SET			\$ <i>Ma</i> 180.00 ✓
S/N TOTAL				\$ 410.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas

\$ 1,400.00 *6001*

To perform wiring checks on electrical systems

\$ 30.00 *201*

To remove, putty, repair, sand and respray affected areas

\$ 800.00 *6601*

To remove, replace & refix bumper sensors

\$ 30.00 ✓

To remove, replace & reinstall Bootlid inner mechansim

\$ 30.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

10A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Signature:

Date:

Date: 27/9/2024
Vehicle No: SNP1934Z
Model: TOYOTA ALPHARD
Chassis: JTNACAAH108001158
Reg.Year: 2024

Third Party Insurer: CTP
Third Party Veh No: GBK5804H
Date of Accident: 27/9/2024
Estimator: JONATHAN
Surveyor:

ESTIMATE

To perform Adas Checks, Calibration & Programming

\$ 800.00 180%

To remove, refix & replace RR Windscreen

\$ 100.00 ✓

LABOUR TOTAL \$ 3,190.00

TOTAL \$ 18,848.25

JONATHAN

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 1/11/2024
Vehicle No: SNP1934Z
Model: TOYOTA ALPHARD
Chassis: JTNACAAH108001158
Reg.Year: 2024

Third Party Insurer: CTP
Third Party Veh No: GBK5804H
Date of Accident: 27/9/2024

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOTLID SUBWOOFER - <i>NA FUNCTION</i>	<i>2152.70</i>		<i>my cm</i> \$2,700.00 ✓
			SUB TOTAL	\$2,700.00
			LESS 25%	-\$675.00
			PARTS TOTAL	\$2,025.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
			S/N TOTAL	\$0.00

SUPPLEMENTARY

LABOUR TOTAL \$0.00

VIC / TING AN TOTAL \$2,025.00

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6484 0019 | Fax: (+65) 6481 1063

Branch

0A Serangoon North Ave 5 Singapore 554909
Tel: (+65) 6484 0019 | Fax: (+65) 6481 1063

Branch (Motor Insurance Claims)

Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

