

JEC AUTO SERVICE PTE LTD

TO	: NTUC	DATE	30/9/2024
VEHICLE NO	: SNP3709 U (2015)		
VEHICLE MODEL	: BMW 318i		Veron.
CHASSIS NO	: WBA8E32080K497626		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Deland</i>	1	\$ 1,301.00	\$ 1,301.00
2	REAR BUMPER SIDE HOLDER <i>cut</i>	1	\$ 185.00	\$ 185.00
3	REAR BUMPER SENSOR <i>new</i>	1	\$ 295.00	\$ 295.00
4	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 56.00	\$ 56.00
8	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00
9	TAILLAMP <i>cut</i>	1	\$ 658.00	\$ 658.00
10	REAR FENDER AIR VENT <i>Deland</i>	1	\$ 78.00	\$ 78.00

TOTAL PRICE: \$ 2,673.00

L' SS 5% \$ 133.65

SUB TOTAL PRICE: \$ 2,539.35

2222
2110.90

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00
2	REAR WHEEL RIM <i>new</i>	1	\$ 800.00	\$ 800.00
3	REAR TYRE <i>new</i>	1	\$ 300.00	\$ 300.00

TOTAL : \$ 1,150.00

50

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 600.00	200	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	400	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 80.00	30	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	X	

TOTAL: \$ 1,580.00

ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,689.35

TOTAL LABOUR COST: \$ 1,580.00

TOTAL REPAIR COST: \$ 5,269.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

710

total : 2870.90

h/s : 2.31c

03 Days.