

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24100033/AVP3E2
Date: 05/12/2024**REFERENCE**

Insured/Claimant:	JALALUDDIN TRAVEL & SERVICES PTE LTD	Policy No:	7220007847
Date of Loss:	28/09/2024	Nature of Claim:	OD Claim No: 4557045546SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE419J	Engine No:	DPCD33433
Make & Model:	AUDI Q2, 1.5 TFSI S TRONIC (A)	Chassis No:	WAUZZZGA1MA035451
Reg. Date:	27/01/2022 (Man. Year: 2021)	Odometer:	49665 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,620.00	3,033.36	11,586.64	79.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,712.00	3,552.00	4,160.00	53.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	22,332.00	6,585.36	15,746.64	70.51
+ GST 9.00/9.00% (\$\$)	2,009.88	592.68	1,417.20	70.51
Nett Amount (\$\$)	24,341.88	7,178.04	17,163.84	70.51

INSPECTION

Date of Assignment:	02/10/2024		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	02/10/2024	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER UPPER	Deformed	1,542.00 FS	*1,233.60 FS
2	1		*REAR BUMPER LOWER	Deformed	1,049.00 FS	*839.20 FS
3	1		*REAR BUMPER TRIM - RH	Deformed	100.00 FS	*79.92 FS
4	1		*REAR BUMPER TRIM - RH	Deformed	68.00 FS	*54.00 FS
5	1		*REAR PARKING AID SUPPORT - RH	Damaged	28.00 FS	*22.08 FS
6	1		*REAR LIGHT REFLECTOR - RH	Not Necessary	36.00 FS	*- FS
7	1		*REAR PARKING AID SENSOR - OUTER	Damaged	286.00 FS	*228.80 FS
8	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
9	1		*REAR REINFORCEMENT BEAM	Not Necessary	707.00 FS	*- FS
10	1		*REAR BUMPER HOLDING STRAP	Not Necessary	17.00 FS	*- FS
11	1		*REAR LID	Repair	2,835.00 FS	*- FS
12	1		*REAR LID ATTACHMENT PARTS	Not Necessary	3,135.00 FS	*- FS
13	1		*REAR LID PACKING ADHESIVE	Not Necessary	23.00 FS	*- FS
14	4		*REAR LID BUNGS	Not Necessary	136.00 FS	*- FS
15	1		*REAR LID LOCK COVER	Not Necessary	15.00 FS	*- FS
16	1		*REAR LID LOCK	Not Necessary	323.00 FS	*- FS
17	1		*AUDI EMBLEM	Necessary	162.00 FS	*129.20 FS
18	1		*Q2 EMBLEM	Necessary	116.00 FS	*92.80 FS
19	1		*REAR LID SPOILER FOAM STRIPS	Not Necessary	162.00 FS	*- FS
20	1		*REAR LID SPOILER FIXING PARTS	Not Necessary	162.00 FS	*- FS
21	1		*1K WINDOW ADHESIVE	Not Necessary	42.00 FS	*- FS
22	1		*REAR WINDSCREEN	Not Necessary	978.00 FS	*- FS
23	1		*PRIMER	Not Necessary	27.00 FS	*- FS
24	1		*TAILLIGHT - RH	Not Necessary	1,656.00 FS	*- FS
25	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	404.00 FS	*322.40 FS
26	1		*SUNDRIES	Necessary	500.00 FS	*31.36 FS
27	1		*PLASTIC PRIMER	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **14,620.00** **3,033.36**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT AND REAR LID WIPER ASSY	New	480.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID	New	2,300.00	1,100.00
5	TO RENEW REAR WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST	New	680.00	0.00
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
8	TO REPAIR REAR END PANEL (Supplementary)	New	250.00	250.00
9	TO RESPRAY REAR END PANEL (Supplementary)	New	550.00	550.00
Gross Labour Cost (\$)			7,712.00	3,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >