

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0731/2024/KS
DATE : 1-Oct-24
WIP : 32768

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

5 Days + 1 Sun - OK - Allan Boo

6-Nov-24

OWNER'S NAME : JALALUDDIN TRAVEL & SERVICES PTE LTD
ADDRESS : BLK 896A TAMPINES STREET 81
#12-854
SINGAPORE 521896
TELEPHONE : HP +65 91006964
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 722007847-02
VEHICLE NO : **SNE 419 J**
MODEL CODE : AUDI Q2 1.5 TFSI S TRONIC
MODEL YEAR : 27/1/2022
ENGINE NO : DPC D33433
CHASSIS NO : WAUZZZGA1MA035451
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Sep-24
PLACE OF ACCIDENT : EAST COAST PARK, SLIP ROAD MERGING INTO ECP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNE 419 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT AND REAR LID WIPER ASSY.	S/N \$	480.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY REAR BUMPER AND REAR LID.	\$	2,300.00	\$ 1,100.00
5	TO RENEW REAR WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	680.00	
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	S/N \$	400.00	
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	\$ 292.00
	ADD LABOUR - SUPPLEMENTARY			\$ 800.00
TOTAL LABOUR CHARGES		: \$	6,912.00	\$ 3,552.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 419 J.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER UPPER	1	\$ 1,542.00	\$	1,233.60
2	REAR BUMPER LOWER	1	\$ 1,049.00	\$	839.20
3	REAR BUMPER TRIM - RH	1	\$ 100.00	\$	79.92
4	REAR BUMPER TRIM - RH	1	\$ 68.00	\$	54.00
5	REAR PARKING AID SUPPORT - RH	1	\$ 28.00	\$	22.08
6	REAR LIGHT REFLECTOR - RH	1	\$ 36.00		
7	REAR PARKING AID SENSOR - OUTER	1	\$ 286.00	\$	228.80
8	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00		
9	REAR REINFORCEMENT BEAM	1	\$ 707.00		
10	REAR BUMPER HOLDING STRAP	1	\$ 17.00		
11	REAR LID	1	\$ 2,835.00		
12	REAR LID ATTACHMENT PARTS	1	\$ 3,135.00		
13	REAR LID PACKING ADHESIVE	1	\$ 23.00		
14	REAR LID BUNGS	4	\$ 136.00		
15	REAR LID LOCK COVER	1	\$ 15.00		
16	REAR LID LOCK	1	\$ 323.00		
17	AUDI EMBLEM	1	\$ 162.00	\$	129.20
18	"Q2" EMBLEM	1	\$ 116.00	\$	92.80
19	REAR LID SPOILER FOAM STRIPS	1	\$ 162.00		
20	REAR LID SPOILER FIXING PARTS	1	\$ 162.00		
SUB TOTAL SPARE PARTS		:	\$ 10,913.00	\$	2,679.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 419 J.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 2,679.60
21	1K WINDOW ADHSEIVE	1	\$ 42.00	
22	PLASTIC PRIMER	1	\$ 100.00	
23	REAR WINDSCREEN	1	\$ 978.00	
24	PRIMER	1	\$ 27.00	
25	TAILLIGHT - RH	1	\$ 1,656.00	
26	REAR WHEEL ARCH COVER - LH / RH	2	\$ 404.00	\$ 322.40
27	SUNDRIES		\$ 500.00	\$ 31.36
TOTAL SPARE PARTS			\$ 14,620.00	\$ 3,033.36
TOTAL LABOUR CHARGES			\$ 6,912.00	\$ 3,552.00
GRAND TOTAL			\$ 21,532.00	\$ 6,585.36

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0731/2024/KS 11-Oct-24 GLORY 1 of 1 SNE 419 J AUDI Q2 1.5 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REPAIR REAR END PANEL.	\$ 250.00	\$ 250.00
2	TO RESPRAY REAR END PANEL.	\$ 550.00	\$ 550.00
GRAND TOTAL		\$ 800.00	\$ 800.00

For Premium Automobiles Pte Ltd

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT