

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24100037/DMA3Q2**Date:** 13/03/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220026226
Claimant Vehicle No :	SHD4811J	Insured Vehicle No :	SLG2321G
Date of Loss:	01/10/2024	Nature of Claim:	TP
		Claim No:	8972489390SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4811J		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU409576
Reg. Date:	16/01/2020 (Man. Year: 2019)	Chassis No:	KMHC851CVLU190190
Colour:	Blue	Odometer:	1580 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,977.06	5,708.60	9,268.46	61.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,460.00	1,910.00	3,550.00	65.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,437.06	7,618.60	12,818.46	62.72
Approved Total (Overridden) (S\$)		6,100.00		
(S\$)	20,437.06	6,100.00	14,337.06	70.15
+ GST 9.00/9.00% (S\$)	1,839.34	549.00	1,290.34	70.15
Nett Amount (S\$)	22,276.40	6,649.00	15,627.40	70.15
+ Car Rental (8.0 x S\$114.78/day) (S\$)		918.24		
+ Loss of Earnings (8.0 x S\$50.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		8,074.49		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment:	03/10/2024	
Date Inspected:	03/10/2024	Inspected At: BIFROST AUTO PTE LTD - LOYANG (HQ) 59 Loyang Drive Level 4 Room 7 Singapore 508969
Estimated Period of Repair:	7.0 days	

Adjuster: BRYAN TANI

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER (RH)	Dented	490.70 FL	*490.70 FL
2	1		*FRONT FENDER SHIELD (RH)	Not Necessary	164.70 FL	*- FL
3	1		*FRT DOOR (RH)	Dented	1,797.20 FL	*1,797.20 FL
4	1		*FRT DOOR RUBBER	Serviceable	250.00 FL	*- FL
5	1		*FRONT DOOR REGULATOR (RH)	Not Necessary	750.40 FL	*- FL
6	1		*FRONT DOOR POWER MOTOR RH	Not Necessary	689.20 FL	*- FL
7	1		*FRONT DOOR HINGE UPPER (RH)	Not Necessary	165.76 FL	*- FL
8	1		*FRONT DOOR HINGE LOWER (RH)	Not Necessary	153.70 FL	*- FL
9	1		*FRONT DOOR CHECK (RH)	Not Necessary	72.98 FL	*- FL
10	1		*FRONT DOOR INNER LOCK (RH)	Not Necessary	385.60 FL	*- FL
11	1		*FRONT DOOR OUTER HANDLE (RH)	Not Necessary	234.80 FL	*- FL
12	1		*FRONT DOOR PROTECTOR (RH)	Cut	186.20 FL	*186.20 FL
13	1		*FRONT DOOR OUTER MOULDING (RH)	Not Necessary	110.10 FL	*- FL
14	1		*REAR DOOR (RH)	Dented	2,147.90 FL	*2,147.90 FL
15	1		*REAR DOOR RUBBER (RH)	Serviceable	280.00 FL	*- FL
16	1		*REAR DOOR OUTER MOULDING (RH)	Not Necessary	125.30 FL	*- FL
17	1		*REAR DOOR OUTER HANDLE (RH)	Not Necessary	124.80 FL	*- FL
18	1		*REAR DOOR CHANNEL (RH)	Not Necessary	358.30 FL	*- FL
19	1		*REAR DOOR GEAR /REGULATOR (RH)	Not Necessary	367.84 FL	*- FL
20	1		*REAR DOOR POWER MOTOR (RH)	Not Necessary	256.80 FL	*- FL
21	1		*REAR DOOR LOCK ASSY	Not Necessary	306.40 FL	*- FL
22	1		*REAR DOOR 1/4 GLASS PILLAR (RH)	Not Necessary	86.70 FL	*- FL
23	1		*REAR DOOR HINGE UPPER (RH)	Not Necessary	173.88 FL	*- FL
24	1		*REAR DOOR HINGE LOWER (RH)	Not Necessary	170.50 FL	*- FL
25	1		*REAR DOOR CHECK (RH)	Not Necessary	85.92 FL	*- FL
26	1		*REAR DOOR PROTECTOR (RH)	Cut	166.20 FL	*166.20 FL
27	1		*ROCKER PANEL OUTER GARNISH	Repair	715.60 FL	*- FL
28	1		*REAR BUMPER	Repair	459.40 FL	*- FL
29	1		*REAR BUMPER SIDE RETAINER (RH)	Not Necessary	85.80 FL	*- FL
30	1		*REAR BUMPER COVER CLIPS	Not Necessary	22.00 FL	*- FL
31	1		*REAR FENDER (RH)	Torn	1,768.30 FL	*1,768.30 FL
32	1		*REAR FENDER SHIELD FRT PIECE (RH)	Not Necessary	165.50 FL	*- FL
33	1		*REAR TYRE RIM (RH)	Not Necessary	1,124.20 FL	*- FL
34	1		*REAR WHEEL HUP-CAP (RH)	Cut	346.40 FL	*346.40 FL
35	1		*REAR WHEELBEARING HUB ASSY	Not Necessary	554.00 FL	*- FL
36	1		*REAR TRAILING ARM (RH)	Not Necessary	265.40 FL	*- FL
37	1		*REAR ASSIST (RH)	Not Necessary	227.90 FL	*- FL
38	1		*REAR SHOCK ABSORBER (RH)	Not Necessary	230.50 FL	*- FL
39	1		*REAR SHOCK ABSORBER MOUNTING (RH)	Not Necessary	133.10 FL	*- FL
40	1		*REAR ABSORBER STOPPER (RH)	Not Necessary	137.60 FL	*- FL
41	1		*REAR ABSORBER COVER (RH)	Not Necessary	175.60 FL	*- FL
42	1		*STABILIZER BAR	Not Necessary	387.30 FL	*- FL
43	1		*STABILIZER LINK (RH)	Not Necessary	147.30 FL	*- FL
44	1		*REAR UPPER ARM (RH)	Not Necessary	239.50 FL	*- FL
45	1		*REAR LOWER ARM (RH)	Not Necessary	393.10 FL	*- FL
46	1		*REAR KNUCKLE ARM (RH)	Not Necessary	538.10 FL	*- FL
47	1		*EMBLEM -BLUE DRIVE (RH)	Necessary	26.60 FL	*26.60 FL
48	1		*FRONT DOOR COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS
49	1		*REAR DOOR TEL NO STICKER (RH)	Necessary	10.00 FS	*10.00 FS
50	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS
51	1		*REAR TYRE (RH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **18,626.08** **7,094.50**
- List Item Discount on L Items 20.00/20.00% (\$) 3,649.02 1,385.90

Total Parts (\$) **14,977.06** **5,708.60**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	700.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	30.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	0.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	0.00
8	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
9	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
10	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
11	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
12	FOUR WHEEL ALIGNMENT	New	120.00	60.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			5,460.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >