

BL Automobile Service

25, Kaki Bukit Road 4 #03-33, Synergy@KB Singapore 417800

UEN Reg No: 53394398A

Tel / Hp :

E-Mail: amylia.blgarage@gmail.com

To: Motor Claims Department

Date: 30/09/2024

Vehicle No: VKM680

Model: Yamaha 135LC SE

Estimated Repair Cost For VKM680 (Yamaha 135LC SE)

QTY	Parts	Amount
1	Front mudguard	\$ 128.60
1set	Front fork	\$ 480.00
1	Front fork bracket	\$ 126.70
1	Front fork bearing	\$ 115.20
1	Headlamp fairing top	\$ 226.70
1set	Headlamp fairing lower	\$ 425.60
1	Headlamp assy	\$ 325.80
1set	Side fairing	\$ 520.00
1	Side fairing inner top garnish o/s	\$ 148.20
1	Side signal lamp o/s	\$ 175.80
1set	Handle bar grip	\$ 175.60
1set	Handle bar balancer	\$ 155.40
1	Brake level	\$ 145.20
1set	Wing mirror	\$ 195.00
1	Brake step pedal	\$ 196.20
1	Side stand	\$ 176.40
1	Step pedal Bracket/Bar	\$ 226.50
1set	Front step pedal	\$ 155.00
1set	Rear side fairing	\$ 405.60
1set	Rear side handle bar	\$ 175.00
1	Rear exhaust pipe	\$ 450.20
1set	Rear exhaust heat guard	\$ 196.80
Parts Sum:		\$ 5,325.50
Parts Less 5% :		\$ 266.28
Parts Total:		\$ 5,059.22

Special Nett Items

1	Front number plate	\$ 32.00
1	Rear number plate	\$ 38.00
1set	Supply fairing sticker	\$ 280.00
Special Nett Items Total:		\$ 350.00

Labour & Misc Charges

Description		Amount
To Remove, Replace, Re-align & Install affected Damaged Areas (\$200.00 per day)	\$	600.00
To Disconnect Wire-Harness to facilitate repairs, Check & Connect Functions	\$	60.00
To Align Body Chassis - Frame	\$	200.00
To Remove Wheel & Balance to Specifications.	\$	20.00
Supply Spray Paint Material & Necessary Items To Respray Affected Body & Frame	\$	800.00
Labour Charges Total:		\$ 1,680.00
Parts Total:		\$ 5,059.22
Special Nett Items Total:		\$ 350.00
Labour Charges Total:		\$ 1,680.00
(Non-Inclusive of GST)	Total Cost Of Repair:	\$ 7,089.22