

BL Automobile Service

25, Kaki Bukit Road 4 #03-33, Synergy@KB Singapore 417800

UEN Reg No: 53394398A

Tel / Hp :

E-Mail: amylia.blgarage@gmail.com

To: Motor Claims Department

Date: 30/09/2024

Vehicle No: VKM680

Model: Yamaha 135LC SE

Estimated Repair Cost For VKM680 (Yamaha 135LC SE)

QTY	Parts	Amount
1	Front mudguard / (V)	\$ 128.60
1set	Front fork / BT	\$ 480.00
1	Front fork bracket / RT	\$ 126.70
1	Front fork bearing / RC	\$ 115.20
1	Headlamp fairing top / (V)	\$ 226.70
1set	Headlamp fairing lower / (V)	\$ 425.60
1	Headlamp assy / (V)	\$ 325.80
1set	Side fairing / (V)	\$ 520.00
1	Side fairing inner top garnish o/s / (V)	\$ 148.20
1	Side signal lamp o/s / (V)	\$ 175.80
1set	Handle bar grip X nn	\$ 175.60 X
1set	Handle bar balancer / (V)	\$ 155.40
1	Brake level (RH) - GR	\$ 145.20
1set	Wing mirror / GR	\$ 195.00
1	Brake step pedal X nn	\$ 196.20 X
1	Side stand X nn	\$ 176.40 X
1	Step pedal Bracket/Bar X nn	\$ 226.50 X
1set	Front step pedal X nn	\$ 155.00 X
1set	Rear side fairing / (V)	\$ 405.60
1set	Rear side handle bar / (V)	\$ 175.00
1	Rear exhaust pipe X nn	\$ 450.20 X
1set	Rear exhaust heat guard X nn	\$ 196.80 X
Parts Sum:		\$ 5,325.50 3748.80
Parts Less 5% :		\$ 266.28 -10%
Parts Total:		\$ 5,059.22 3373.92

Special Nett Items

1	Front number plate / RC	\$ 32.00
1	Rear number plate X RH	\$ 38.00 X
1set	Supply fairing sticker / RC	\$ 280.00

Special Nett Items Total: \$ 350.00 170

Labour & Misc Charges

Description	Amount	
To Remove, Replace, Re-align & Install affected Damaged Areas (\$200.00 per day)	\$ 300	600.00
To Disconnect Wire-Harness to facilitate repairs, Check & Connect Functions	\$ 30	60.00
To Align Body Chassis - Frame	\$	200.00 X
To Remove Wheel & Balance to Specifications.	\$	20.00 ✓
Supply Spray Paint Material & Necessary Items To Respray Affected Body & Frame	\$ 200	800.00
Labour Charges Total:	\$	1,680.00
		550
Parts Total:	\$	5,059.22
Special Nett Items Total:	\$	350.00
Labour Charges Total:	\$	1,680.00
Total Cost Of Repair:	\$	7,089.22

(Non-Inclusive of GST)

Steve (LKK)
 30/9/24, 11.01 am
 m l
 L/S
 by 11 sky
 4 days
 repair limit \$3K

4093.92

L/S - 3275.13
 = 3200

Repair limit \$3000

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: .

Date: