

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 64739722

Co Reg No : 197701469G

ESTIMATE

GST R	eg No-	:	MR-8500111-X
-------	--------	---	--------------

Invoice Name & Address	Owner Name & Vehicle Info				
Mr Lee Woi Cye Louis	Cust No/Name KCV20188/Mr Lee Woi Cye Louis				
The Lee wor eye Lours	Reg No/Reg Date SMD8449L / 07/09/2018				
Block 9 Geylang East Avenue 1	Date In/Mileage 17/10/2024/ 109158				
#15-15	Chassis No JMAXTGK1WJZ003224				
Singapore 389783	Engine No 4B40DT1743				
Contact No Mobile: 86857272	Make/Model MIT/ECLIPSE CROSS 1.5 T/C SPORTS (
17/10/	Colour/Trim P26 ORIENT RED / BK BLACK				

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00147	Cash	20/11/2024/ 19:32	TLL	1210/ Lim Teng Keat	50965		
Description of Goods / Services			Qty	Unit Price	Disc%	Amount	
A 28000001							320.00
TO REMOVE	E & REPL	ACE REAR EXHAUST MUFF	FLER				
X RIVET, FR	BUMPER			10.00	5.00	00.00	50.00
X COVER, RR	BUMPER,	RH		1.00	170.00	00.00	170.00
X BUZZER, KI	EYLESS OF	PERATIO,RR		1.00	96.00	00.00	96.00
X MUFFLER,	EXHAUST I	MAIN		1.00	545.00	00.00	545.00
X CLIP, RR I	BUMPER			8.00	26.00	00.00	208.00
X PANEL AS	SY, TAILG	ATE		1.00	1125.00	00.00	1125.00
X SENSOR, BA	ACK DIST	ANCE WARN		1.00	348.00	00.00	348.00

Estimate

Confirm & accepted by

Nett 2,862.00 9% GST on 2862.00 257.58

Total Payable 3,119.58

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.