

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

21/10/2021

Vehicle No:

SQ3345X

Brand & Model:

MINI One 5 Door RHD

Chassis/VIN No:

WMW22DK0302R45565

WIP#:

28313

Date:

30-Sep-24

Franchise:

MINI

Contact Person (Eurokars):

WONG

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES							MARK = Survey Marking [Key "A" if item is approved]	
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE		
1	REAR BUMPER	M51.12.5.A3C.AC1	1	A	\$ 831.35	\$ 831.35		
2	KIT ADD-ONS	M51.12.5.B39.770	1	A	\$ 146.97	\$ 146.97		
3	LOWER BUMPER TRIM	M51.12.5.A3C.AC5	1	A	\$ 247.65	\$ 247.65		
4	TOWING COVER	M51.11.9.450.684	1	A	\$ 54.41	\$ 54.41		
5	BUMPER COVER LOWER	M51.11.5.A40.E35	1	A	\$ 134.68	\$ 134.68		
6	REAR PDC HOLDER SET	M51.12.5.A3C.AC7	1		-	\$ 92.95		
7	GUIDE FOR BUMPER LH	M51.11.9.450.585	1		-	\$ 216.32		
8	GUIDE FOR BUMPER RH	M51.11.9.450.586	1	A	\$ 216.32	\$ 216.32		
9	BLIND RIVET	M07.14.7.411.141	4	A	\$ 16.12	\$ 16.12		
10	HEX BOLT	B07.14.9.213.164	1	A	\$ 2.15	\$ 2.15		
11	REAR REINFORCEMENT	M51.12.7.300.788	1	A	\$ 652.73	\$ 652.73		
12	WASHER-GASKET	B51.12.7.300.789	2	A	\$ 30.94	\$ 30.94		
13	REVERSE SENSOR	B66.20.9.274.428	2		-	\$ 701.10		
14	SENSOR SEAL	B66.20.9.283.203	4	A	\$ 29.40	\$ 29.40		
15	TAILGATE	M41.00.7.378.205	1		-	\$ 2,231.64		
16	SUPPORTING MOUNT TOP	M51.62.7.337.600	1		-	\$ 83.33		
17	MOUNT RAIL, LH	M51.13.7.375.109	1		-	\$ 31.79		
18	MOUNT RAIL, RH	M51.13.7.328.384	1		-	\$ 31.79		
19	NUT	M51.12.7.046.911	2		-	\$ 7.02		
20	BLIND RIVET	B51.24.8.226.003	4		-	\$ 21.84		
21	SLIDER	B51.62.7.401.793	4		-	\$ 43.96		
22	NUT	B51.12.7.020.321	2		-	\$ 2.86		
23	EXPANDING NUT	M51.13.8.253.546	4		-	\$ 4.68		
24	BREATHING COVER	51 12 7302547	1	A	\$ 116.29	\$ 116.29		
25	C CLIP	07 14 7311312	1	A	\$ 1.63	\$ 1.63		
26	EMBLEM ONE	51 14 2755615	1	A	\$ 76.18	\$ 76.18		
27	UNDERBODY PANEL	51 75 7315819	1	A	\$ 114.72	\$ 114.72		
28						\$ -		

Sub-Total (Parts Price) \$ 2,671.54 \$ 6,140.82

LABOUR / SERVICES CHARGES			
NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER, TAILGATE AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,440.00	\$ 2,860.00
2	TO RESPRAY REAR BUMPER AND TAILGATE.	\$ 1,840.00	\$ 2,880.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	-	\$ 250.00
4	TO TRANSFER THE TAILGATE MECHANISM.	-	\$ 920.00
5	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	-	\$ 560.00
6	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	-	\$ 195.00
7	TO INSTALL THE TAILGATE STICKER.	\$ 350.00	\$ 350.00
8	TO TRANSFER THE REVERSE SENSORS.	\$ 180.00	\$ 500.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
11	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days:5	Excess:
---------------------	---------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ 4,100.00 \$ 9,165.00

	REVISED	PRICE
Parts Price	\$ 2,671.54	\$ 6,140.82
Labour Price	\$ 4,100.00	\$ 9,165.00
Total (Initial Estimate)	\$ 6,771.54	\$ 15,305.82
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ 6,771.54	\$ 15,305.82
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ 6,771.54	\$ 15,305.82
GST 9%	\$ 609.44	\$ 1,377.52
GRAND TOTAL	\$ 7,380.98	\$ 16,683.34