

ASS. REC. BY:

REF:

ICS/ CS/ICS24100041/Kvp3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

MPC24A00005000

Claims No.

DMPC2401311H/ST

Sum Insured:

Excess:

0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$26K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/10 11:00 @ 5400k Carhu (red 4237.80, 43%)

Veh No:

SLA 284A

Yr Regn:

01, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru XV

C.C.

1600

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp.Reading

119256

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JF1GP3KC5FG151041

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

29/9/24

D.O.I.

2/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S L/R O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	284G

Vehicle Details

Vehicle No.:	SLA284A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2024
Vehicle Make:	SUBARU
Vehicle Model:	SUBARU XV 1.6I-S AWD CVT
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	FB161647302
Chassis No.:	JF1GP3KC5FG151041
Maximum Power Output:	84.0 kW (112 bhp)
Open Market Value:	\$17,706.00
Original Registration Date:	22 Jan 2016
First Registration Date:	22 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$17,706.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Jan 2026
PARF Rebate Amount:	\$9,738.00

Intended COE Rebate Details

COE Expiry Date:	21 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,002.00
COE Rebate Amount:	\$5,879.00
Total Rebate Amount:	\$15,617.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.
The information contained herein is correct as at 30 Sep 2024

OK

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24A00005000	Date of Loss:	29/09/2024
Vehicle Reg. No.:	SLA284A	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NIRMAWATI BANTE ABDUL RAHMAN		
Driver:	ABDUL RAHMAN AHMAD ZAINI		
Make/Model:	SUBARU XV, 1.6 (A)	Vehicle Reg. Date:	22/01/2016
Vehicle Colour:	WHITE	Chassis No:	JF1GP3KC5FG151041
Engine No:	FB161647302		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6 ✓		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

*Not Whited
1/1 Rm @ 5400/h
Repair After Peim
Ex TBA*

COST OF CLAIMS

	Amount
Parts	6,487.80
Miscellaneous Items	330.00
Labour	2,820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,637.80
+ GST 9.00% (S\$)	867.40
Nett Amount (S\$)	10,505.20

This claim is handled by: GOH JACQUELINE

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 01 Oct 2024)

Parts: 144

SUBARU XV 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Accord Auto Services Pte Ltd/SLA284A/01/10/2024 16:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET	0.00	0.00	Ry *800.00 F	✓
2	2		*FRONT BONNET HINGE	0.00	0.00	Dil *120.00 F	✓
3	1		*FRONT GRILLE BASE	0.00	0.00	Sn *95.00 F	X
4	1		*FRONT GRILLE CHROME *SURROUND	0.00	0.00	Dil *140.00 F	✓
5	1		*FRONT EMBLEM	0.00	0.00	Sn *45.00 F	✓
6	1		*FRONT GRILLE CHROME *CENTRE	0.00	0.00	CM *80.00 F	✓
7	1		*FRONT BUMPER	0.00	0.00	CM *290.00 F	✓
8	2		*FRONT BUMPER SIDE RETAINER LH & RH	0.00	0.00	Dil *60.00 F	✓
9	1		*FRONT HEADLAMP RH	0.00	0.00	Mit *580.00 F	✓
10	1		*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	CM *40.00 F	✓
11	1		*FRONT FOGLAMP RH	0.00	0.00	Mit *250.00 F	✓
12	1		*FRONT FOGLAMP LH	0.00	0.00	Mjcm *250.00 F	✓
13	1		*FRONT BUMPER SPONGE	0.00	0.00	Bu *45.00 F	✓
14	1		*FRONT REINFORCEMENT	0.00	0.00	Ry *160.00 F	✓
15	1		*FRONT BUMPER TOW COVER	0.00	0.00	Sn *8.00 F	X
16	1		*FRONT FENDER RH	0.00	0.00	Ry *200.00 F	✓
17	1		*FRONT FENDER INNER SHIELD RH	0.00	0.00	Tn *90.00 F	✓
18	1		*FRONT WHEEL ARCH RH	0.00	0.00	Bu *70.00 F	✓
19	1		*FRONT FENDER TOP MOULDING RH	0.00	0.00	Dil *150.00 F	✓
20	1		*FRONT FENDER LH	0.00	0.00	Bu *160.00 F	✓
21	1		*FRONT FENDER INNER SHIELD LH	0.00	0.00	CM *90.00 F	✓
22	1		*FRONT FENDER TOP MOULDING LH	0.00	0.00	Sn *150.00 F	X
23	1		*FRONT WINDSCREEN GARNISH RH	0.00	0.00	Sn *80.00 F	X
24	1		*RADIATOR	0.00	0.00	TT/Pn *400.00 F	✓
25	1		*RADIATOR FAN MOTOR	0.00	0.00	Sn *150.00 F	X
26	1		*RADIATOR FAN COWLING	0.00	0.00	Sn *90.00 F	X
27	2		*RADIATOR STOPPER LOWER	0.00	0.00	Sn *20.00 F	X
28	1		*RADIATOR STOPPER TOP	0.00	0.00	Sn *30.00 F	X
29	1		*RADIATOR TOP HOSE	0.00	0.00	Sn *45.00 F	X
30	1		*RADIATOR LOWER HOSE	0.00	0.00	Sn *45.00 F	X
31	1		*AIR CLEANER BOX	0.00	0.00	Mjcm *35.00 F	✓
32	2		*AIR CLEANER BOX AIR DUCT	0.00	0.00	Mjcm *170.00 F	✓
33	1		*FRONT DOOR RH	0.00	0.00	R *500.00 F	X
34	2		*FRONT DOOR HINGE RH	0.00	0.00	R *140.00 F	X
35	1		*FRONT DOOR CHECKER RH	0.00	0.00	Sn *30.00 F	X
36	1		*FRONT DOOR RUBBER RH	0.00	0.00	Sn *250.00 F	X
37	1		*FRONT DOOR STICKER RH SET	0.00	0.00	Sn *40.00 F	X

F=Franchise part.

Sub Total (S\$)	5,898.00
+ Margin on L,N Items 10.00% (S\$)	589.80
Total Parts (S\$)	6,487.80

Accord Auto Services Pte Ltd/SLA284A/01/10/2024 16:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER CLIPS	50.00 ✓
2	1	FRONT DOOR INNER COMPARTMENT CLIPS	50.00 X
3	2	FRONT FENDER INNER SHILED LH & RH	180.00 ✓
4	1	FRONT NUMBER PLATE WITH HOLDER	50.00 45.00
Sub Total (S\$)			330.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,200.00 1000
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,200.00 800
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00 20
4	TO APPLY ANTI RUST TREATMENT	New	120.00 X 2
5	TO REMOVE/REFIX/REPLACE FRONT RH DOOR GLASS, INNER COMPARTMENT, MECHESMISM & ETC TO NEW DOOR	New	200.00 X 200
Gross Labour Cost (S\$)			2,820.00

Accord Auto Services Pte Ltd/SLA284A/01/10/2024 16:03. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: