



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: ANDY SEAH		Ref: CS/LIP24060193/Anh3m4(N) Date: 28/07/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 5259H	Veh. Inspected	WUV 9322
Policy No.		Coverage (\$)	0.00
Claim No.	AVS24/1949	Excess (\$)	0.00
Assign From	ANDY SEAH	Assign Date	24/06/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA INNOVA	c.c	1998
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	PN111NV4008623901	Colour	GREY
Odometer	277278 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65R15	HANKOOK	6 mm
L/H Front Tyre	205/65R15	HANKOOK	6 mm
R/H Rear Tyre	205/65R15	HANKOOK	6 mm
L/H Rear Tyre	205/65R15	HANKOOK	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/06/2024	Inspection Date	25/06/2024
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)REGISTRATION DATE: 28 JAN 2011 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	