

TSL AUTO PRO SELECTION PTE LTD

TO	: LIBERTY	DATE	25/6/2024
VEHICLE NO	: WUV9322 (2011)	<i>Hui Rong</i>	
VEHICLE MODEL	: TOYOTA INNOVA		
CHASSIS NO	: PN111NV4008623901		

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT			
PARTS (LIST ITEMS)							
1	REAR BUMPER Deformed		758.90	✓			
2	REAR BUMPER SIDE HOLDER New		36.90	+			
3	REAR BUMPER LOWER BRACKET @50.60 New		101.20	+			
4	RERA BUMPER LOWER REFLECTOR @48.90 LH could		97.80	48.90			
5	REAR BUMPER SENSOR @241.60 LH piece excluded		483.20	241.60			
6	REAR END PANEL Dented		687.20	✓			
7	REAR END PANEL TOP GARNISH Deformed		266.50	✓			
8	TAILLAMP @410.20 LH could		820.40	410.20			
9	TAILLAMP PANEL New		361.20	+			
10	TAILGATE Distorted		1392.40	✓ 1210			
11	TAILGATE LOCK Dend		215.50	✓			
12	TAILGATE WEATHERSTRIPE cut		298.60	✓			
13	TAILGATE OUTER CHROME MOULDING Cracked		352.90	✓			
14	TAILGATE INNER TRIM BOARD Deformed		598.90	✓			
15	TAILGATE GLASS MOULDING new		187.10	✓			
16	TOYOTA LOGO	5717.60	60.50	✓			
17	INNOVA EMBLEM		70.90	✓			
18	TOYOTA WORDING		49.20	✓			
19	2.0 EMBLEM		40.20	✓			
20	G EMBLEM		38.10	✓			
21	REAR FENDER New	4288.20	1358.90	+			
22	REAR FENDER INNER SHIELD New		62.30	+			
23	REAR FENDER INNER TRIM BOARD @601.20 New		1202.40	+			
24	REAR FENDER GLASS MOULDING New		70.40	+			
25	REAR EXHAUST PIPE		794.10	+			
26	REAR EXHAUST PIPE MOUNTING		39.60	+			
27	REAR EXHAUST PIPE GASKET		32.70	+			
28	REAR EXHAUST PIPE HEAT SHIELD		105.70	+			
Wiper motor			Less	25%	10583.70	25%	
					2645.93		
					7937.78		
SPECIAL NETT ITEMS							
1	REAR BUMPER CLIPS New		30.00	✓			
2	REAR BUMPER LOWER SPOILER Distorted		1200.00	800			
3	REAR END PANEL TOP GARNISH CLIPS New		20.00	✓			
4	REAR END PANEL SEALANT New		60.00	✓			

5	TAILGATE OUTER CHROME MOULDING CLIPS <i>new</i>	30.00	✓
6	TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	30.00	✓
7	TAILGATE GLASS SEALANT <i>new</i>	60.00	✓
8	REAR CAMERA <i>new</i>	480.00	+
9	REAR FENDER INNER SHIELD CLIPS <i>new</i>	20.00	+
10	REAR FENDER INNER TRIM CLIPS <i>new</i>	30.00	+
11	REAR FENDER GLASS SEALANT @40 <i>new</i>	80.00	+
12	REAR NUMBER PLATE <i>new</i>	30.00	+
Total Parts		2070.00	

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	OUR ASSESSMENT (\$)
	LABOUR		
1	PANEL BEATING	1800.00	800
2	SPRAY PAINTING	1600.00	800
3	WIRING	100.00	30
4	TO APPLY TUFF COAT	150.00	60
5	TO REMOVE UPHOLSTERY	150.00	60
6	TO TRANSFER TAILGATE FITTINGS	150.00	60
7	TO REMOVE TAILGATE GLASS	180.00	120
8	TO REMOVE REVERSE SENSOR	100.00	50
11	TO REMOVE REAR FENDER GLASS	100.00	X
12	TO REMOVE REAR EXHAUST PIPE	150.00	X
13	TO REMOVE REAR CAMERA	100.00	50
Labour Total :		4580.00	
TOTAL (PARTS & LABOUR):		14587.78	

2030

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total 7348.20

h/s: 581c

06 Days

581c