

ASS. REC. BY: Taufikh REF: CS/1M124100043/Tup3

ASSIGNMENT

CoE 2025/07

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ch. ang Vehicle: IN / OUT

Veh No: SHD 3292 M Yr Regn: 2016, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41UMGUD9182

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: 1.6 / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 27

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Davanti

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 02/00/24

Survey held at

Comfort Layan

Des. of Damages: F/R / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Battery weak</u>
	<u>Taufikh confirmed lump sum \$2600 and 4 days (red, \$3376.32, 56%)</u>

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 4

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

☐ : Final Report

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

/ Rep. Format:

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	28/09/2024
Vehicle Reg. No.:	SHD3292M	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	08/07/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDFU504540	Chassis No:	KMHLB41UMGU091882
Odometer:	106152 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	4,034.32
Miscellaneous Items	12.00
Labour	1,930.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,976.32
+ GST 9.00% (S\$)	537.87
Nett Amount (S\$)	6,514.19

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG **Version:** 1.0 (Last Synchronised: 01 Oct 2024)**Parts:** 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3292M/01/10/2024 16:53**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	de *553.00 FL
2	1		*REAR BUMPER BRACKET SIDE /RH	20.00	0.00	cur *35.00 FL
3	10		*REAR BUMPER CLIPS	20.00	0.00	cur *22.00 FL
4	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	cur *32.00 FL
5	1		*REAR BUMPER REINFORCEMENT	20.00	0.00	x *428.40 FL
6	1		*REAR BUMPER LOWER COVER	20.00	0.00	de *228.00 FL
7	1		*BOOTLID LAMP RH	20.00	0.00	cur *565.60 FL
8	1		*TAIL LAMP RH	20.00	0.00	cur *697.80 FL
9	1		*EXHAUST MUFFLER RH	20.00	0.00	RP *1,935.40 FL
10	1		*REAR BUMPER MAT	20.00	0.00	cur *50.00 FL
11	2		*REAR FENDER ADVERTISEMENT LH/RH	20.00	0.00	cur *200.00 FL
12	1		*BOOTLID ADVERTISEMENT	20.00	0.00	x *100.00 FL
13	1		*REAR BUMPER ADVERTISEMENT	20.00	0.00	cur *60.00 FL
14	1		*REAR REVERSE SENSOR	20.00	0.00	x *135.70 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,042.90
- List Item Discount on L Items (S\$)	1,008.58

Total Parts (S\$)	4,034.32
--------------------------	-----------------

ComfortDelGro Engineering Pte Ltd/SHD3292M/01/10/2024 16:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

12.00

Sub Total (S\$)

12.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

600

950.00

2 SPRAY PAINTING

New

560

800.00

3 REMOVE/REFIX REVERSE SENSOR

New

30

60.00

4 CHECK LIGHTING /WIRING

New

30

60.00

5 TUFF COATING

New

X

60.00

Gross Labour Cost (S\$)

1,930.00

ComfortDelGro Engineering Pte Ltd/SHD3292M/01/10/2024 16:53. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Jia Min 97495749
 wp 2/6/24 C 430pm.
 c/s Resurvey after repair
 Tan Jia Min 2/11/2024
 3-4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 01.10.2024 16:20

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5956086

JC NO305605705

OMER

REGN NO.:
SHD3292M

MILEAGE

S COMFORT TRANSPORTATION PTE LTD

MAKE:
HYUNDAI

FUEL

OMER NO. 7010045

E.....1/2.....F

ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

MODEL I-40 28.09.2024 22:22

(R) 65508755 (O)

YR OF MANU.
08.07.2016

TARGET DATE

(P)

CHASSIS CODE
KMHLB41UMGU091882

COMPLETION DATE/TIME:


JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 28.09.2024

ATURE: 3P 28.09.2024

NO	LABOR CODE	DESCRIPTION
----	------------	-------------



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.:
SHD3292M

o.: SHD3292M CHIANG

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard