

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24100044/TVP3M4**Date:** 15/10/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZC05842
Claimant Vehicle No :	SHC1499C	Insured Vehicle No :	SNJ775D
Date of Loss:	01/10/2024	Nature of Claim:	TP
		Claim No:	M2405714

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1499C		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU081777
Reg. Date:	13/09/2018 (Man. Year: 2018)	Chassis No:	KMHC851CVKU107526
Colour:	Blue	Odometer:	524572 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,583.04	2,538.40	44.64	1.73
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,360.00	970.00	390.00	28.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,955.04	3,520.40	434.64	10.99
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	3,955.04	2,800.00	1,155.04	29.20
+ GST 9.00/9.00% (S\$)	355.95	252.00	103.95	29.20
Nett Amount (S\$)	4,310.99	3,052.00	1,258.99	29.20

INSPECTION

Date of Assignment:	02/10/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	02/10/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 15 Oct 2024)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1499C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	481.10 FL	*481.10 FL
2	1		*FRONT BUMPER BRACKET /RH	Not Necessary	55.80 FL	*- FL
3	1		*FRONT BUMPER UPPER MOULDING	Cut	368.50 FL	*368.50 FL
4	1		*FRONT FENDER EMBLEM	Necessary	26.60 FL	*26.60 FL
5	1		*HEAD LAMP RH	Cut	2,110.30 FL	*2,110.30 FL
6	1		*FRONT BUMPER GRILLE RH	Cut	186.50 FL	*186.50 FL
					Sub Total (S\$)	3,228.80 3,173.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	645.76 634.60
					Total Parts (S\$)	2,583.04 2,538.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	380.00
2	SPRAY PAINTING	New	600.00	560.00
3	CHECK LIGHTING AND WIRING	New	60.00	30.00
Gross Labour Cost (\$)			1,360.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >