



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100045/Rnp3m4
16 RAFFLES QUAY	Date:	03/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7746K	Veh. Inspected	SGA 11E
Policy No.	-	Coverage	0
Claim No.	D24008576MFCT	Excess	\$0.00
Assign From	KARENT	Assign Date	01/10/2024

2. Vehicle Details

Make & Model	PORSCHE PANAMERA V6 PDK E5	C.C	3605
Engine No.	D02471	Year of Reg.	13/11/2013
Chassis No.	WP0ZZZ97ZDL000615	Colour	WHITE
Odometer	116280 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/40ZR20	PIRELLI	7
L/H Front Tyre	255/40ZR20	PIRELLI	7
R/H Rear Tyre	255/40ZR20	PIRELLI	7
L/H Rear Tyre	255/40ZR20	PIRELLI	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/08/2024	Inspection Date	02/10/2024
Survey held at	27A TANJONG PENJURU (S) 609042 – REPAIRER: EUROKARS GROUP		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days