

REPAIR ESTIMATE

Name & Address:

Motor Claims Department

MS FIRST CAPITAL INSURANCE LTD

16 Raffles Quay, #42-01

Hong Leong Building

Singapore 048581

Email/Fax No:

Contact No:

Type of Claim:

THIRD PARTY

YEAR MODEL:

13/11/2013

Vehicle No:

SGA11E

Brand & Model:

Panamera

Chassis/VIN No:

WP0ZZZ97ZDL000615

WIP:

12834

Date:

30-Sep-24

Franchise:

PORSCHE

Contact Person (Eurokars):

FAIZ

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>SM ✓</i>	P970-505-911-41-	1		-	\$ 2,732.50
2	TOWING COVER <i>XAN</i>	P970-505-703-00-GZL	1		-	\$ 54.10
3	BUMPER SENSOR <i>? xsv ✓</i>	P150-919-275-C-G2L	1		-	\$ 360.90
4	SENSOR GASKET <i>SM ✓</i>	P7PP-919-133-	6		-	\$ 40.20
5	RETAINING FRAME RH <i>? xsv ✓</i>	P970-505-564-03-1E0	1		-	\$ 116.50
6	RETAINING FRAME (RH) LOWER <i>? xsv ✓</i>	P970-505-544-02-1E0	1		-	\$ 186.40
7	DISC (RH) <i>? xsv ✓</i>	P970-505-574-00-1E0	1		-	\$ 155.10
8	DISC BLACK MAT RIGHT LOWER <i>? xsv ✓</i>	P970-505-576-00-1E0	1		-	\$ 155.10
9	FIXING DEVICE <i>SM ✓</i>	P970-505-719-00-	2		-	\$ 79.80
10	SUPPORT BRACKET RH <i>? xsv ✓</i>	P970-505-554-00-	1		-	\$ 30.40
11	FRONT BUMPER RETAINER RH <i>? xsv ✓</i>	P970-505-536-02-	1		-	\$ 57.60
12	BRACKET FOR HEADLIGHT WASHER <i>SM ✓</i>	P999-507-998-40-	2		-	\$ 9.00
13	RETAINER PLATE LH FOR HEADLIGHT WASHER LH <i>SM ✓</i>	P970-505-325-00-	1		-	\$ 100.90
14	RETAINER PLATE RH FOR HEADLIGHT WASHER RH <i>SM ✓</i>	P970-505-326-00-	1		-	\$ 100.90
15	EXPANSION RIVET <i>SM ✓</i>	PPAF-038-549-	8		-	\$ 6.40
16	BUND RIVET <i>SM ✓</i>	P999-190-104-30-	8		-	\$ 16.00
17	ADDITIONAL HEADLIGHT RH <i>? xsv ✓</i>	P970-631-082-05-	1		-	\$ 777.00
18						\$

Sub-Total (Parts Price) \$ - \$ 4,978.80

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR FRONT FENDER RH & ALL AREAS AFFECTED BY THE ACCIDENT.	1720	\$ 4,360.00
2	TO RESPRAY FRONT BUMPER, FRONT FENDER RH	2600	\$ 2,800.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	ANX	\$ 250.00
4	TO TRANSFER THE FRONT BUMPER SENSORS.	nett	\$ 250.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00

7	SUNDRIES	nett	\$ 20 ✓
---	----------	------	---------

Survey Date & Time	Repair Days	Excess:

Surveyor Remarks:

- Remarks:
- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
 - An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$	-	\$	8,750.00
			REVISED	PRICE
Parts Price	\$	-	\$	4,978.80
Labour Price	\$	-	\$	8,750.00
Total (Initial Estimate)	\$	-	\$	13,728.80
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	13,728.80
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	13,728.80
GST	9%	\$	-	1,235.59
GRAND TOTAL	\$	-	\$	14,964.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 9001w68
4 days
02/10/24
Reg by paint